

Douglas County Surveyor's Record of
Government Corners Renewed

23 T. S. 10 R. W. W. M.

Corner to Sections $\frac{27}{34} \frac{26}{35}$ (Corner 200 ft. E. of Creek) 19

Old Post located - Original B.T.'s. burned out.

Reset Post with 4" x 3" Red Cedar Post.

Mark Trees: 20" Cedar N.23°W., 5 ft.
28" Fir N.8°30'E. 33 ft.
18" Hemlk S.51°W. 31 ft.

SEE CORNER NO. 59

$\frac{1}{4}$ Section Corner to Sections 26 & 35. 20

No trace of Orig. BT's. (Burn) at 27 + 50 ch. an 18" Cedar
mkd. & blazed by Cruiser - 18 ft. No. of line.

Set 3" x 3" x 4' Fir Post for $\frac{1}{4}$ Corner.

20" Fir N.65°E. 44 ft.
18" Fir N.39°E. 39 ft.

SEE CORNER NO. 58

Section Corner to Sections $\frac{26}{35} \frac{25}{36}$ 21

Set Fir Post 3" Sq.

60" Fir N.25°E. 20 ft.
52" Fir S.50°E. 19 ft.
50" Fir S.89°W. 18 ft.
48" Fir N.55°W. 9 ft.

SEE CORNER NO. 26

$\frac{1}{4}$ Corner to Sections 11/12. 22

Found $\frac{1}{4}$ Post Sec. 11/12 which was partially rotted and one BT.

Replaced Post with 4"x 4"x 4' Red Cedar Post.

30" Fir N.70°E. 20 ft. - Orig. BT.
12" Fir N.78°W. 8 ft.

SEE CORNER NO. 20

M/C of Fractional Sec. 11 & 12. 23

Found Original BT's. of Meander Corner but unable to find Post, so

Set 3" x 3" x 4' Cedar Post for M/C of fractional Secs. 11 & 12.

20" Alder S.48°E. 16.5 ft. - Orig. BT's
40" Fir S.48°W. 75.4 ft. -
15" Alder N.17°W. 12.8 ft.
18" Alder N.37°E. 6.5 ft.

SEE CORNER NO. 39

Meander Corner for 11/12. 24

Set 3"x 3"x 3' Fir Post at High Watermark of Lake for M/C 11/12.

8" Fir N.78°E. 28.5 ft.
24" Fir S.19°W. 39.0 ft.

SEE CORNER NO. 48

For M/C 2/1 - Sighted Across Lake and Set Stake at Water's edge. 25

Set 4"x 4"x 4' Fir Post
12" Ash S. 6°E. 22 ft.
10" Ash N.63°W. 13 ft.

Renew Section Corner to Sections 25, 26, 35, & 36. 26

Found - The 4 Orig. BT's. All check for bearing & distance, size &
species. All have been rebark scribed about 20 years ago.
I believe that they were rescribed by the same person who
scribed the BT's. for State Lands. I find very old scribe
Marks on S.W. BT. which I believe to be Original.

Set Brass Cap at Corner Marked: $\frac{26}{35} \frac{25}{36}$ T.23S, R.10W. County Surveyor's
Office, 1957

Existing BT's alive & good condition. All Bark scribed. I do not
rescribed or scribe any BT's. Note - All distances to faces of BT's.

SEE CORNER NO. 60

OREGON STATE BOARD OF FORESTRY
1933 Filed 4/24/58
C. S. File No. 49/80

James W. Hyron, Deputy
M. Godfrey
S. Blouw
August, 1957
C. S. File No. 49/60

Rev. 21