

Douglas County Surveyor's Record of
Government Corners Renewed

T 24 T. S. R 1 R.W.W.M.

KORE-CHAPMAN CO., EUGENE, ORE. 21881

149

Douglas County
Surveyors Office
Larry E. Monrean
Randall W. Smith
Oct. 13, 1986
C.S. 59/30

Section corner for Secs. 13, 14, 23 and 24
REFERENCED CORNER ONLY
Found monument and accessories as described in last renewal. #113
From found DCSO brass disk and iron pipe set: #152
Bearing Object 1, a 5/8" iron rod with alum. cap, bears N.05°E.,
524.52 ft.
Bearing Object 3, a 5/8" iron rod with alum. cap, bears N.33°E.,
557.83 ft.
Bearing Object 4, a 5/8" iron rod with alum. cap bears N.49°E.,
418.82 ft.
Corner is approx. 80 ft. west of F.S. Rd. #24-1-1.0. Area is to be
logged in near future, section corner will probably be destroyed.
Sketch and horizontal directions are filed in C.S. 59/30.
NOTE: SEE ADDENDUM BELOW

RE-RENEWED
SEE CORNER NO. #152

150

Douglas County
Surveyors Office
Larry Monrean
Deputy
R.W. Smith and
S.J. Flaseue
Oct. 3, 1986
C.S. 62/38

1/4 Corner for Sections 13 and 24.
Found - Corner monument searched for but not found.
Orig. BT, 6" now 8" diam. Fir now dead has fully healed blazes,
we opened upper blaze, scribing found "1/4S" bears
N.26°E., 20.5 ft. (Rec. N.82°E., 20.5 ft.) Bearings of BTs
appear to be in error. Blaze orientated S.26°W.,
30" Diam. Orig. D. Fir with a fully healed single blaze, We
opened blaze, scribing found "BT" about 1 1/2 inches deep in
tree. Growth rings are too dense to make accurate count. BT
bears S.82°E., 21.1 ft. (Rec. S.23 1/2°E., 21.1 ft.) The blaze is
orientated N.82°W.
Set - Apparent record bearing recording problem is best resolved by
interchanging bearings of trees while retaining BT quadrant and
distance. Blaze orientation supports this idea.
At position as noted, set a 1" x 32" galv. iron pipe with brass cap
marked "Douglas County Surveyors T24S 1/4 S13 S24 RIW 1986
Office". Monument protrudes 9 inches above ground.
New BTs - 11" diam., D. fir double blazed and scribed "1/4 S13 CS BT" bears
N.12 1/4°W., 20.0 ft.
6" Diam. D. fir double blazed and scirbed "1/4 S24 CS BT" bears
S.30 1/2°W., 10.4 ft.
Corner lies approx. 250 ft. northerly of an east-west ridge on a steep
northeast slope.

10/3/86

Douglas Co.
Surveyors Office
Randall Smith
S.J. Flause
Nov. 17, 1986
C.S. 59/30
MOVED TO
CS 64/3-2

***ADDENDUM TO SECTION CORNER, 13, 14, 23 and 24 (Ren. No. 149)
Area of section corner to be logged in near future. To protect against
corner loss we pull up and replace DCSO brass cap/iron pipe per Ren. #113
with a DCSO drill cap marked as noted: DOUGLAS COUNTY SURVEYORS OFFICE
T24S S14 S13 S23 S24 RIW 1986. #152
Drill cap set in bedrock. Several PK nails driven in rock surrounding
brass cap and three boat spikes set randomly over brass cap for future
magnetic locating. Drill cap is set 18" under ground surface.
PK nails with flagging set in base of bearing trees, PK nails are
oriented approx. at corner.

RE-RENEWED

11/17/86

151

Thomas D. Scherner
For: Woodstock
Logging
June 19, 1989
C.S. 63/85

Section Corner for Secs. 33 and 34; and 4 & 3 of T.25-1
Found - County monument dated 1966 leaning at 45° angle but not
displaced. Ren. #60. Straightned monument and placed stones
at base.
Checked measurements to BTs, found OK.
Found all BTs per notes of County Surveyors Office, 1966, with
the following exceptions:
Orig. 48" fir now a stump.
Two new BTs set by County, 1966, are Doug. fir; Orig. 6" fir
is a hemlock.
No new accessories established. Corner is now in recent cut-over.

6/19/89