

Douglas County Surveyor's Record of
Government Corners Renewed

Twp 24 S. T. S. Rge. 2 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

V. W. Hasford, Surveyor

April 1952

C.S. FILE #11/27

SECTION CORNER, SECTIONS 22, 23, 27 and 26:

- 1 1/2" Iron Pipe found four original B. T.s
- 14" Cedar N. 21 degrees West, 16.3 Ft. Marked)
R 2 W - S 22)
- 12" Fir N. 52 1/2 degrees East, 30.8 Ft. Marked)
T. 24 S. - S 23) P.S. 253 B.T.
- 12" Hemlock S. 17 degrees East, 12.0 Ft. Marked)
R 2 W - S 26)
- 12" Hemlock S. 42 degrees West, 9.0 Ft. Marked)
T 24 S - S 27)

1/4 CORNER SECTIONS 27 and 26:

- Found original stone monument
- Marked 1/4 Sec. 27, 16" Fir N. 29 degrees West, 86 Ft.) P.S.
- Marked 1/4 Sec. 26, 20" Fir N. 33 degrees East, 40.0 Ft.) 253 B.T.

MID 1/4 SECTION CORNER 26 :

- 1 1/2" Iron Pipe
- 12" Cedar S. 65 1/2 degrees West, 30.2 Ft.
- 14" Hemlock N. 82 1/2 degrees East, 37.1 Ft. (1/4 S. 26
(P. S. 253 B. T.)

1/4 CORNER SECTIONS 26 and 25:

- 1 1/2" Iron Pipe - found original trees both dead
- 26" Fir, Marked 1/4 Sec. 26, S. 59 degrees West, 9.0 Ft.) P.S.
- 26" Fir, Marked 1/4 Sec. 25, N. 9 degrees East, 34.3 Ft.) 253 B.T.

Section Corner to Section 14, 15, 22, & 23.

Before logging in this area I found the two yew and the one cedar bearing trees, described in the original notes, in good condition. The original marked stone corner was gone, and the 40 inch Fir BT. was a windfall. After logging, only the original Cedar BT remained. From this tree I determined the position of the corner and drove a 2" iron pipe 30" long 18" in ground, from which:

- A Hemlock 28" in Diam. bears S. 56 1/2° E., 77.9 ft. mkd. T24S, R2W S22 PS 253 B.T.
- A Cedar 30" in diam. bears S. 15° W. 15.8 ft. (orig. BT) mkd. T24S, R2W S22 PS 253 B.T.
- A Yew 12" in diam. bears N. 70° W., 75.4 ft. mkd. T24S R2W S15 253 B.T.

No suitable tree remained standing in N.E. Quadrant.

Sept. 13, 1957

1/4 Section corner to Sections 14 & 15.

Before logging both original bearing trees were in good condition. After logging the B.T. for section 14 is a stump and the B.T. for Section 15 is dead and down. At the true point of the corner, I drove a 1 1/2" iron pipe 30" long, 18" in the ground, from which:

- A Hemlock 11" in diam. bears N. 86° E. 53.4 ft. mkd. 1/4 S 14 253 B.T.
- A Hemlock 36" in diam. bears S. 62° W. 58.1 ft. mkd. 1/4 S 15 253 B.T.

8/27/69 SEARCHED FOR NOT FOUND "VRT" Sept. 13, 1957

1/4 Section Corner to Sections 15 & 22.

After logging in Section 22, only one bearing tree remained. The vine Maple bearing tree (scribed in bark) for Section 22 is in good condition. At the true point of the corner I drove a 2" iron pipe 30" long, 18" in the ground, from which:

- A Hemlock 12" in diam. bears N. 1/2° W. 24.2 ft. marked 1/4 S 15 253 B.T.
- A Hemlock 24" in diam. bears S. 85 1/2° E. 65.2 ft. marked 1/4 S 22 253 B.T.

Sept. 13, 1957

Remonumentation of 1/4 Section 14 & 23.

After logging in Section 14, both original bearing trees were in good condition. At the true point of the corner, I drove a 1 1/2" iron pipe 24" long, 16" in the ground.

Sept. 13, 1957

V. W. Hasford, surveyor

Sept. 13, 1957

C. S. File No. 42/306

FO. OK 11/177
Rep. out File No.
C.S. Section -
C.S. 59/30

RE-RENEWED, SEE CORNER NO #113

RE-RENEWED, SEE CORNER NO 71

1

2

3

4

5

6

7

8