

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 24

T. S.

R 5

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21891

109

Douglas County Surveyors Office
Larry E. Monrean
Terrie Frannsen
Coleen Bliss
August 1, 1986
C.S. 62/37

Section Corner for Secs. 25 and 36; and 30 and 31 of T.24-4
Found - 1" x 36" Gal. I.P. with 1958 County brass cap out of ground.
Was able to identify location for corner by depression in
ground and location of broken flanged base of monument
under surface. Renewals 7 and 22
W. Oak now a 26" dia. stump with blaze visible in growth ring
pattern bears N.59°W., 39.8 ft.
12" W. Oak N.32°E., 59.5 ft. Has been cut down.
14" W. Oak now a 16" dia. snag with well healed blaze bears
S.79°W., 32.0 ft.
16" W. Oak now a 22" dia. stump bears S.25°E., 60.8 ft.
(stump located on easterly edge of creek bed.)
Orig. 16" maple N.61½°E., 46.2 ft. Not found. (this position
falls at westerly edge of creek bed.)
14" B. Oak now 18" dia. and cut down bears N.37½°W., 13.2 ft.
(Rec. N.38°W., 13.0 ft.)
Set - We reset monument with cap protruding approx. 1 foot above
ground, We add the words "RESET 1986".

New Accessories:

10" B. Oak blazed and scribed "T24S R4W S31 CS BT" bears
S.62½°E., 15.7 ft.
8" W. Oak blazed and scribed T24S R4W S30 CS BT" bears
N.47½°E., 52.6 ft.
Set ½" x 8" spike in 18" stump of down bearing tree. Spike bears
N.37½°W., 13.2 ft. and stamped "B0".

All BTs tagged with DCSO Bearing tree tags.

*FD 9/15/88
B. SHAWER
C.S. 62/35*

110

Douglas County Surveyors Office
Randall Smith
Stephen Flause
Jan. 10, 1989
C.S. 62/61

Section Corner for Secs. 33 and 34; and Secs. 3 and 4 of T.25-5
Found - A 3/4" I.D. iron pipe 45" long out of ground leaning against
fence. Per Ren. #13 Also see Renewals 34 and 61
A hole 1½ ft. long by 6" wide and 6" deep was found at probable
corner position.
16" now 36" dia. D. fir with a fully healed single blaze bears
N.70½°E., 33.8 ft. (Rec. N.72½°E., 33.8 ft.)
18" now 26" dia. D. fir with a fully healed double blaze bears
S.24°E., 57.2 ft. (Rec. S.22½°E., 58.0 ft. dist. is a possible
slope measurement.)
No other BTs found.
Set - A 2½" dia. brass cap on a 30½" long, 1 3/8" O.D. iron pipe is set
at North end of previously described hole as the most probable
position of section corner. Brass cap/iron pipe protrudes 7"
above ground. 3/4" I.P. is set along south edge of BC/IP and
protrudes 5" above ground.

No new accessories.

Corner is approx 13 ft. south of a four way fence corner in south running
fence line. Section corner is also the SW DLC corner #40 in T24-5.

1/10/89

1/4 Corner for Sections 24 and 25

Found - A 1960 County 2½" daim. brass cap properly mkd., on a 1½" O.D.
iron pipe is severely bent to north where it protrudes 12"
from ground. Ren. #54 (When mon. is referenced and removed
it is found that I.P. is 36" long).

10" W. Oak now a 16" DBH W. Oak with a fully healed single blaze
bears S.67°W., 85.3 ft. (Rec. S.67°W., 85.8 ft., a slope dist.)
Ren. No. 54

10" W. Oak now a double trunked W. Oak, the westerly trunk of which
is 16" DBH and has a fully healed double blaze. Center of root
crown of double trunked Oak bears N.59°E., 89.0 ft. dist. Ren.54

No clear evidence of the orig. bearing tree is found.

Set - Plumb position of found monument is referenced out. Mon. is removed
and in the ref. position is established a new monument with a
2 3/8" dia. B.C. mkd. "Douglas County Surveyors Office T24S R5W
1/4 S24 S25 1989" on a 1 3/8" O.D. 32" long galv. I.P. set
protruding 4" above ground.

New BT - A 14" D.B.H. W. Oak double blazed and scribed "1/4 S25 CS BT"
bears S.69°E., 55.0 ft. distant.

3/28/89

Douglas County Surveyors Office
R. W. Smith and
S. Flause
March 28, 1989
C.S. 62/61

*FO OK 11-92
BY BENTZ M116-42
FD OK 6-93
BY WARE 1993-0042*