

Douglas County Surveyor's Record of
Government Corners Renewed

25

T. S.

1

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

L. E. Monrean, Doug. Co. Surveyors Office
P. L. Earle
Sept. 13, 1976
C.S. 59/24

128

Section corner for Secs. 13 and 24 only.

Found - 48" (rec. 60") Fir, now a stump, bears N.74°W., 29.0 ft. with blaze. I open & find scribing "T25S R1W S13 BT".
Stone, 16"x14"x7" (rec. 6"x10"x8" above ground, orig. 12"x10"x8") found 3 notches on opposite faces and S 13 on another face. Rock has been dislodged by windfall bearing tree.

38" Fir (rec. 36") is now a windfall. Tree has well healed blaze. Steel tube with survey cap, dislodged by uprooted BT. Ren. #22

Set - Brass cap at section corner stamped:

"County Surveyors Office"
1976

R	T 25 S	R
1	S 13	S 18 1
W	S 24	E

Set - Corner stone on north side of cap, set steel tube on south side of cap.

5/8" x 30" Iron rod with alum cap. in BT stump, bears N.75°W., 28.7 ft. Cap stamped "B.O. 1".

Spike in 40" Fir stump, bears S.50°W., 33.8 ft. stamped "B.O. 2".

Cedar post 2" square x 9 ft. Set post 2.4 ft. in the ground, bears north, 4.0 ft.

9/13/76

1/16 Corner for Sec. 4 and Sec. 33 of T24-1.

Found - 3/4" x 36" steel tube with alum. cap stamped "USPC property cor." T25S R1W 33

4 E 1/16 RE 4287

Steel tube is bent, cap is 16" above ground. Area disturbed by An 8" Red Cedar, now a stump, bears S.71°W., 14.2 ft. (Rec. S.70°W., 9.7 ft.) Stump scribed "BT".

NE BT not found.

Renewal:

Due to the condition of the monument (bent & loose) and the tie to the SW BT, I determine that the monument has been disturbed.

I remove the corner monument and place in the position where I found it, and I.R. 3/4" x 30" long, 27" in the ground.

I set - monument, marked as noted at corner as determined by T.E. Shrum Jr., M 32 - 62,

From which: an 8" Red Cedar stump bears S.70°W., 9.7 ft.

3.4" I.R. bears N.80°E., 4.3 ft.

New BT: Set 3/8" x 12" star drill 10" deep at center of a 48" Hemlock stump. Marker bears S.41 1/2°W., 31.9 ft. Stump blazed and scribed "1/16 S4 CS BT". Note: Star drill used is a 1/2" drill, shank portion measures 3/8".

12/9/76

1/4 Corner for Secs. 23 and 26

Found - No monument found. Area of corner lies on area cat bladed for fire trail. Ren. #106

Orig. 10" Fir, now dead, 15", bears N.35°W., 3.3 ft. Tree has well healed blaze. We open and find scribing "1/4 S23" Growth rings indicate extremely slow growth.

Orig. 18" now 22" Cedar is down and lodged against NW BT.

Scribing visible in unhealed blaze "1/4 S BT"

A 5" Cedar bearing S.12°W., 47.2 ft. dislodged for cat trail. Has well healed blaze.

A 8" D. Fir bearing N.73°W., 23.6 ft. is uprooted, partially buried, open blaze (unhealed) scribing found "1/4 S23 CS".

Set - A 1" x 30" Iron Pipe 26" in the ground with brass cap attached stamped:

"Douglas County Surveyor" 1 T 25 S R 1 W
1977 / 4 S 23
S 26

New BT's- Set R.R. Spike in a 36" Fir stump. Spike bears S.50°W., 37.7 ft. Spike stamped "B.O".

A 12" D. Fir bears N.54 1/2°W., 25.1 ft. Tree double blazed and scribed "1/4 S23 CS BT".

Note: This corner lies on EW cutting line. Area clear cut to the South.

5/5/77

129

130

Larry E. Monrean
P. L. Earle
Doug. Co. Surveyors
Office
Dec. 9, 1976
C.S. 59/26

Larry E. Monrean
R. B. Kimberling
P. L. Earle
Doug. Co. Survey-
ors Office
April 5, 1977
C.S. 59/34

3-77