

Douglas County Surveyor's Record of
Government Corners Renewed

25 T. S. 2 R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 97196

36

Section Corner to Sections 22, 23, 26, & 27.
Found - Rock with 2 notches on S. & 2 notches on E. edges.
60" Pine, now 72" N.37°E. 38.9 ft., showing good scar.
30" Fir, now " S.25°E. 21.1 ft., showing good scars.
26" Fir, now 37" N.44°W. 38.9 ft., showing good scar.
The tree to the S. W. is down but the Stump Hole checks
for bearing & distance. Cut out part of upper scar &
found scribed "R 2 W S27".
Set Iron Pipe with Brass Cap at Corner alongside Rock & Mkd:
County Surveyor's Office, 1958 T25S R2W $\frac{S22}{S27} \frac{S23}{S26}$
Blaze & Scribe 4" Hemlock S.83°W. 22.3 ft. scribed "S27 CS BT"

RE-RENEWED, SEE CORNER NO. #125

James W. Byron, Deputy
M. Godfrey
S. Bilow
July 14, 1958
C.S. File No. 49/102

ED. 10/13 M 51-27

37

$\frac{1}{4}$ Section Corner to Sections 22 & 23.
Found - Rock Mkd. " $\frac{1}{4}$ " on W. Side.
Hemlock, now 16" diam. S.55°W. 7.9 ft. (" $\frac{1}{4}$ " S2" now visible)
Set Brass Cap at Corner Mkd: $\frac{1}{4}$ S22/S23 T25S R2W County Surveyor's
Office, 1958
New BT's: 60" Fir Stump S.77°E. 39 ft. scribed " $\frac{1}{4}$ S23 CS BT."
11" Hemlock S.86 $\frac{1}{2}$ °W. 40 ft. scribed " $\frac{1}{4}$ S22 CS BT".

July 23, 1958

38

$\frac{1}{4}$ Section Corner Common to Sections 8 & 17.
No trace of the Orig. Corner Post or BT. in Section 8.
8" Hemlock, which from the corner bears S.6°W. 20 lbs. is orig.,
still standing & now 16" diam. From this tree the position
of the corner was determined & at this point I drove a $1\frac{1}{2}$ " Iron
Pipe 36" long, 24" in ground & marked new BT.:
A Hemlock 15" diam. bears N.75°W. 29.9 ft. mkd. $\frac{1}{4}$ S8 253 B.T.
Beside the Iron Pipe, I set a 4" Cedar Post mkd. $\frac{1}{4}$ S 8 & 7 253.

V. W. Hosford.
For Evans Products Co.
Nov. 10, 1958
C. S. File No. 42/398
M 13 - 13

39

Center $\frac{1}{4}$ Section Corner of Section 8.
Drove a $1\frac{1}{2}$ " Iron Pipe 36" long 24" in the ground, from which:
A Hemlock 16" diam. bears S.42°W. 13.6 ft. Mkd. C $\frac{1}{4}$ S8 253 B.T.
A Hemlock 16" diam. bears N.13 $\frac{1}{2}$ °W. 13.6 ft. mkd. C $\frac{1}{4}$ S8 253 B.T.
Beside the Iron Pipe I set a 4" Hemlock post mkd. C $\frac{1}{4}$ S8 253.

FDCK
5/5/58

40

Section Corner to Sections 19, 20, 29 & 30.
Found - Stone at Corner & 3 Original BT's:
Orig. 10", now 20" Chinquipin N.65°E. 17.8 ft., shows good scribing,
rescribe "S20 T25S R2W".
Orig. 8", now 14" Chinquipin S.69°E. 13.9 ft., shows good
scribing "BT", also rescribed. Both BT's have old scars.
Orig. 20", now 30" Cedar shows old scar with rotted face,
S.24°W. 19.8 ft.
No trace of Orig. N.W. BT. found.
Set Brass Cap alongside Corner Stone Mkd: Bounty Surveyor's Office,
 $\frac{S19}{S30} \frac{S20}{S29}$ T25S R2W CS BT. 1959
New BT's: 10" R.Cedar bears S.37°E. 21.5 ft. scribed S29 T25S R2W CS BT.
30" R.Cedar bears S.24°W. 20.3 ft. scribed S30 T25S R2W CS BT.
11" R.Fir bears N. 3°W. 28.0 ft. scribed S19 T25S R2W CS BT.
7" R. Fir bears N. 5°E. 15.9 ft. scribed S20 T25S R2W CS BT.
Note - I also find 2" x 2" scribed Stake at Corner.

PO. OK
3/8/81
2. P. 822
C.S. 58/236

James W. Byron, Deputy
Milo Godfrey
S. A. Bilow
C. Putnam
C. S. File 49/102 June 25, 1959

41

$\frac{1}{4}$ Corner to Sections 16 and 21.
Found - Brass Cap at Corner. B.B. Irving. REN. #3
S.W. BT. is O.K., shows good scribing.
N. W. BT. is gone in new roadway construction.
New BT: 22" Cedar bears N.57°E. 65.0 ft. scribed $\frac{1}{4}$ S16 CS BT.

July 13, 1960
C.S. File
No. 49/102