

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 T. S. R 6 R.W.W.M.

KORE-CHAPMAN CO., EUGENE, ORE. 21991

C O N T - - -

Doug.Co. Surveyors
R.W. Smith - S.J.
Flause
Sept. 9, 1988
C.S. 62/55

($\frac{1}{4}$ Cor. 8 and 9)

191

New BTs - A 6" DBH W. oak, double blaze and scribed " $\frac{1}{4}$ S9 CS BT" bears S.72 $\frac{1}{2}$ °E., 13.4 ft.
A 9" DBH D. fir double blazed and scribed " $\frac{1}{4}$ S8 CS BT" bears S.55°W., 33.7 ft.
Monument lies in N-S fence line at easterly edge of farm access road and approximately 60 ft. south from C/L of Cole Road #91.

(9/9/88)

Section Corner for Sections 6 and 7; and 1 & 12 of T.25-7

CORNER REPORT ONLY

192

Found - 1" iron pipe with 2 $\frac{1}{2}$ " brass cap, 1963 County Cap, from which:
38" D. fir now a snag 10 ft. high, bears S.2°W., 11.9 ft.
24" D. fir now a 6 ft. high stump, face overgrown, bears Ren# N.55°E., 4.2 ft. 144
36" D. fir now a 6 ft. high stump, face overgrown bears S.5°E., 19.0 ft.
24" D. fir now a snag face overgrown, bears N.38°W., 4.5 ft.
16" D. fir now a 10 ft. high snag, face burnt off, bears S.22°W., 21.8 ft.

Corner lies on a gentle west slope, approx. 80 ft. west of dirt road along summit of Tyee Mt.

1/4 Corner for Section 6; and Section 1 of T.25-7

193

CORNER REPORT ONLY

Found - 1" iron pipe with 2 $\frac{1}{2}$ " brass cap erroneously marked "County Surveyors Office W $\frac{1}{4}$ S6 T25S R6W R7W 1963" from which: Ren. # 143
36" D. fir now a rotten stump bears S.38°E., 42.2 ft.
36" D. fir face overgrown bears S.58 $\frac{1}{2}$ °W., 71.9 ft.
8" D. fir face overgrown bears N.76°E., 12.2 ft. (USBLM record 21.4 ft.) (Vol. 36 Pg. 14949, 1967)
10" D. fir face overgrown bears S.26 $\frac{1}{4}$ °E., 21.4 ft. (USBLM record 12.2 ft.)

Apparently there was a transcription in USBLM notes on above 2 trees' distances. Also, BLM notes say that the above corner erroneously marked and is actually common to both sections 6 and 1.

The corner lies west approx. 80 ft. from the main road (dirt) along the top of Tyee Mt. ridge.

Center 1/4 Corner for Section 6

194

Set - 1" x 36" iron pipe with a 2 $\frac{1}{2}$ " brass cap marked "C $\frac{1}{4}$ S6 RLS 430 1989".

New BTs - 10" D. fir BT I scribed "C $\frac{1}{4}$ BT" bears S.77°W., 35.9 ft.
10" D. fir BT I scribed "C $\frac{1}{4}$ BT" bears N.70°E., 2.2 ft.

1/4 Corner common to Section 6; and Sec. 31 of T.24-6

195

CORNER REPORT ONLY

Found - 2 $\frac{1}{2}$ " iron pipe with a 3 $\frac{1}{4}$ " brass cap marked "U.S.B.L.M. Cadastral Survey, $\frac{1}{4}$, S31, T24S R•W S6 T25S R6W 1967" from which:
18" D. fir face overgrown, bears N.14 3/4°W., 72.6 ft.
30" D. fir BT face overgrown, bears S.32°W., 29.2 ft. (Record 31.7 ft.)

The corner is north approx. 80 ft. from the top of a spur ridge that slopes down to SE. Many mistakenly blazed property lines and BTs in the area south of corner approx. 100 ft.

Bruce Shaner Engineering
For: Western Timber Company
July 28, 1989
C.S. 63/96 and RM 3 - 72

NEXT PAGE