

Douglas County Surveyor's Record of
Government Corners Renewed

T 25

T. S.

R 7

R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97101

134

Howard Johnstone
L.S. 98
For: Roseburg Lbr. Co.
August 10, 1983
M 94 - 63

Section corner for Secs. 12 and 13 only of T.25-8
Found - 1962 County brass cap and iron pipe in root wad of blown down
SW BT. Ren. #68A
18" fir, S.55°W., 23.1 ft. part. healed
22" fir, N.18°W., 62.0 ft. leaning
52" fir, S.85°W., 10.6 ft. down.
30" fir, S.65°E., 17.8 ft. down and rotted.
Set - Reset brass cap iron pipe at record bearing and distance from
standing BTs.
New BT - 13" cedar, S.67°E., 28.2 ft.

8/10/83

135

Burton W. Holt
L.S. #418
For: Sun Studs
May 13, 1985
C. S. 63/8

1/4 Corner between Section 31; and Section 6 of T.26-7
Found - 1971 BLM brass cap and
20" fir bears S. 30° W., 16.2 ft.
Note: This area was to be logged in 1984 so I removed the pipe and brass
cap and replaced with a 5/8" x 30" iron rod set deep in the
ground, in the exact position of the pipe and brass cap.
After the logging and slash burning, I RESET the pipe and brass
cap in its original position putting it directly over the iron rod.
New Accessory:
The original BT is now a 20" fir stump 7 ft. tall. I rescribed
the tree "1/4 S BT" and nailed a bearing tree tag on west side
facing road.
Corner is on a landing 50 ft. east of road. No other trees available.

5/13/85

136

Howard Johnstone
L.S. #498
For: Roseburg
Resources and Kenneth
Ford Aug. 17, 1987
M 104 - 55

Center 1/4 Corner for Section 6
Set - 5/8" x 36" iron rod with aluminum cap marked "LS 498".
BTs - 19" fir bears S.83°W., 7. 2 ft.
15" fir bears S.17°E., 8.5 ft.
3/4" iron pipe bears S.82°16'25"W., 29.61 ft. per 1969 BLM
administrative survey.

8/17/87

137

Shaner Engineering
For: Western
Timber Co.
July 1989
C.S. 63/96
RM 3-72

CORNER REPORT ONLY
Section Corner for Sections 1 and 12; and Secs. 6 and 7 of T.25-6
Found - 1" iron pipe with 2 1/2" brass cap (1963 County) and from which:
38" D. fir now a snag 10 ft. high bears S.2°W., 11.9 ft.
24" D. fir now a 6 ft. highstump face overgrown bears N.55°E.,
4.2 ft. Ren. #74
36" D. fir now a 6 ft. high stump face overgrown bears S.5°E.,
19.0 ft.
24" D. fir now a snag face overgrown, bears N.38°W., 4.5 ft.
16" D. fir now a 10 ft. high snag face burnt off, bears S.22°W.,
21.8 ft.
Corner lies on a gentle west slope, approx. 80 ft. west of road along
summit of Tye Mt.

138

1/4 Corner for Section 1; and Section 6 of T.25-6
CORNER REPORT ONLY Ren.#73
Found - 1" iron pipe with a 2 1/2" brass cap erroneously marked "County
Surveyor's Office W 1/4 S6 T25S R6W R7W 1963" from which:
36" D. fir now a rotten stump bears S.38°E., 42.2 ft.
36" D. fir face overgrown bears S.58 1/2°W., 71.9 ft.
8" D. fir face overgrown bears N.76°E., 12.2 ft. (USBLM record
21.4 ft.) Vol. 36 Pg. 14949 Ren. No. 73
10" D. fir face overgrown bears S.26 1/4°E., 21.4 ft. (USBLM record
12.2 ft.)
Apparently there was a transcription in USBLM notes on above two trees.
Also, BLM notes say that the above corner is erroneously marked and is
actually common to both sections 6 and 1.
The corner lies west approx. 80 ft. from the main road (dirt) along the to 1/2
of Tye Mt. ridge.