

Douglas County Surveyor's Record of
Government Corners Renewed

T. 26 S. T. S. R. 8 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Vernon Tracy &
Crew
C.S. File No. 54/72

MARCH 71

1/4 Corner to Sections 27 and 34. 44
Found - Orig. 72", now 74" Fir, now snag, S. 24°W. 30.4 ft. ^{#68} open &
shows scribe marks.
Orig. 36" Fir, now 42" decayed stump, N. 26°W. 56.8 ft., no scribe.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office T. 26 S R 8 W
1970 S 27
S 34
New BT's: 14" D. Fir N. 67°E. 21.4 ft. mkd: "1/4 S27 CS BT".
15" D. Fir S. 7°E. 7.3 ft. mkd: "1/4 S34 CS BT".
This corner lies on nearly flat southerly slope.
There is a Weyerhaeuser Co. Tag on a 14" Fir N. 28°W. 27.0 ft.,
no "W" found. See Also C.S. 18/55.

Section Corner common to Secs. 15, 16, 21 and 22. 7/14/70
Found - 50" Fir, N. 83°E., 19.1 ft. Scar visible. 45
12" Myrtle, S. 47°E., 38.3 ft. Rotted face.
Ground Depression, N. 58°W., 11.2 ft.
Post Gone.
Set - 1 1/2" Iron pipe with brass cap. Referenced with
"W" nails and plates.
New BT's: 44" Fir, S. 61°W., 79.9 ft.
14" W. Fir, N. 78°W., 35.5 ft.
22" Hemlock, S. 44E., 53.6 ft.

1/4 Corner common to Sections 15 and 22. 46
Found - 16" Fir stump, N. 45°W., 30.4 ft. Scribe visible.
18" P.O. Cedar, S. 62°W., 7.9 ft. Scar visible.
Set - 1 1/2" Iron pipe with brass cap. Referenced with "W"
nails and plates
New BT's: 22" P.O. Cedar, N. 25°E., 32.0 ft.

Section Corner common to Sections 14, 15, 22 and 23. 47
Found - 24" Fir, N. 41°E., 25.1 ft. Scar visible.
Rotted Stump, S. 25°E., 30.4 ft.
20" Fir, Downed, S. 51°W., 27.7 ft. Scar visible.
16" Fir, Downed, N. 22 1/2°W., 43.6 ft. Scar visible.
Set - 1 1/2" Iron pipe with brass cap. Referenced with "W"
nails and plates.
New BT's: 8" Hemlock, S. 15°W., 26.1 ft.
16" Hemlock, S. 63°E., 19.5 ft.
8" Hemlock, N. 61°W., 30.7 ft.

1/4 Corner common to Sections 22 and 23. 48
Found - 24" Fir, (snag), N. 30°E., 9.9 ft. Rotted Face.
28" Fir, (snag), N. 25°W., 21.1 ft. Scribe visible.
Set - 1 1/2" Iron pipe with brass cap. Referenced with "W"
nails and plates.
New BT's: 22" Fir, S. 66°E., 9.5 ft.
30" Fir, N. 57°W., 3.9 ft.
Note - Face of 24" BT in NE quadrant badly rotted. Small por-
tion of smooth face and ax marks still visible.
Face of 28" BT in NW quadrant also badly rotted. How-
ever by chopping a hole in back of BT a small part
of positive scribe is visible.

1/4 Corner common to Sections 22 and 27. 49
No evidence found of "X" on rocks or of 8" BT.
Set - 1 1/2" Iron pipe with brass cap. Referenced with
"W" nails and plates.
New BT's: 16" Fir, N. 43 1/2°W., 3.6 ft.
20" Fir, S. 01°W., 25.0 ft.

FO. OK
8/85 BY:
MICHAEL McDowell
WEYERHAEUSER CO.
M 99-18

Triangle Engineering Co.
Nick Juliano
May, 1972
C.S. 55/251
M 44 - 79