

Douglas County Surveyor's Record of
Government Corners Renewed

27 T. S. 3 R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21861

Section Corner between sections 23,24,25,and 26 122 Ren. #27
Found: an iron pipe, firmly set, with brass cap attached, marked

COUNTY SURVEYORS OFFICE

T 27 S
S23 S24
S26 S25
R 3 W

Gary L Langlitz
A Vic Cangie
M Lenora Ladig
Marie Garriott
9/2/75
CS 57/36

Note: The section locations shown on the brass cap are correct, however, the cap is stamped to be read from the north side.

The original bearing trees are all down and in various stages of decay. We find Milo godfrey's trees marked in 1947 as follows:

- A hemlock bearing approx. S 1°W.,10.3 ft., is down, scribe buried.
- A Hemlock bearing approx. S85°E.,23.3 ft., is down with scribe marks visible.

We mark the following new bearing trees:

- a 7" Hemlock bears N84°W.,15.4 ft., scribed: "T27S R3W S23 CS BT" on a double blaze.
- A 27" D.Fir bears S 1/2°E.,53.8 ft., scribed:"T27S R3W S 25 CS BT" on a single blaze. No other trees near. Compass declination setting: 20° East.

123

1/4 Corner to Sec. 7 & 8

Found: Orig. 24" D.Fir now a 30" Snag bearing S 80°E.,13.9ft., No marks visible. The Original N.W. bearing tree has been destroyed

- A 22" now 26" Madrone marked by Cadastral engineers in 1958 bears S 84 1/2°E., 35.6ft., with scribing visible on unhealed blaze.
- A 13" now 18" incence cedar in good condition ,also marked in 1958 bears N65° W.,37.6ft., with scribing visible on unhealed blaze.

The BLM brass cap set in 1958 has been destroyed. At the corner point, we set a 1"x30: Iron pipe, with brass cap attached, Marked:

DOUGLAS CO. SURVEYOR
1975

T 27 S
1/4
S7 | S8
R 3 W

Gary L Langlitz
Peter L Earle
Jim H. Cook
CS 57/36
9/24/75

Note: The scribing on the NW bearing tree has been partially defaced by fire. We rescribe, "1/4 S7 CS BT" on a single blaze above the present blaze. This corner is located on a steep north slope along an old cat fire trail. Compass declination setting: 20° East.

1/4 Corner to Sec.7&18

124

Found - U.S. Bureau of Land Management Cadastral Survey Brass Cap properly stamped(1958)

Note cap on lower side of logging skid road under 1.5ft of fill. Found wooden stake squared at top, broken off at surface, bottom portion of stake located beside base of brass cap monument.

BT's-A cedar, 15" now 18" in dia. bears N 32 1/2°W.96.1 ft.(Rec.N35 1/2°W., 95.7 ft.) scribed " 1/4 S7 BT" Upper portion of bearing tree is dead, has 35" dia fir log lodged against westerly side.

A 34" dia. fir (a windfall)

The approximate center of standing location bears S 10 1/2°W,57.4 ft.(rec.S 6 W) Tree lies facing downhill toward corner

REnewal-as monument is 1.5 feet below surface I reference position of monument and replace monument at referenced position with brass cap above surface at corner point.

New BT's-A cedar 18"dia. bears S85°W.,114.5 ft. scribed"1/4 S 18 CS BT"

11/14/75

L.E.Monrean
P.L.E.
C.S. 57/39
11/14/75

*FDX
Deders
11/2006 4157-61*

7/6