

Douglas County Surveyor's Record of
Government Corners Renewed

T. 27 $\frac{1}{2}$ S. T. S. R. 8 W. R.W.W.M.

Section Corner to Sections 32 & 33 only, T.27 $\frac{1}{2}$ -8W.

Found - Only shattered remains of one BT:

18" Hemlock N.22 $\frac{1}{2}$ °W. 66.7 ft., dead, shattered stump, fragmentary scribe on portion of blaze.

No trace of N. E. BT. or 1961 Brass Cap at corner point.

Set - Brass Cap at Cor. Mkd: County Surveyor's T27 $\frac{1}{2}$ R8W S 32 | S 33
Office, 1970 T28

New BT: 30" Hemlock N. 4° W. 112.4 ft. mkd: "T27 $\frac{1}{2}$ S R8W S32 CS BT."
(This is only suitable tree close)

This corner was destroyed by large rocks rolling down from new Burnt Mtn. Access Road construction and lies on very steep, N.E. slope/
The Standard corner of Sections 4 & 5, T28-8W is 42.9 ft. S.88°E.

5/5/70

Standard Corner to Sections 4 and 5, T28-8W.

Found - 1961 Cadastral Brass Cap in pipe with 2" I.P. alongside.

Orig. 32" Hemlock S.81°E. 7.3 ft., alive & tagged.

12" Hemlock, alive, S.36°E. 50.2 ft., tagged, blaze nearly healed.

All other BT's. gone, due to large rocks & logs in fill of new Burnt Mts. access road.

New BT; 32" Hemlock S.1 $\frac{1}{2}$ °W. 63.5 ft. mkd: "T28S R8W S5 SC CS BT".

This corner lies on very steep, easterly slope approx. 125 ft. W. of Wilson Creek, course N. W.

5/15/70

North 1/4 Corner to Section 32, T.27 $\frac{1}{2}$ S., R.8W.

Found - 1961 Cadastral Brass Cap.

Orig. BT's: Cedar 22" dia. S.72 $\frac{1}{2}$ °E. 46 lks., scribe visible #11
but now a shattered stump.

Hemlock 40" dia. S.36°W. 107 lks. scribe not visible now a stump.

New BT: Scribed: 6" dia. Yew S.41°E. 17.7 ft. "1/4 S 32 BT."

All of Section 32 has been clear cut. There are no other trees suitable for bearing trees.

April 18, 1973

1/4 Corner Sec. 32. (South)

Found - A 2 1/2" x 28" I.P. with 1961 BLM brass cap attached marked:
"T 27 1/2 S R 8 W" Cadastral Survey

1/4 S 32
1961

Cap is 24" above ground and leaning. Bearings and distances to bearing trees indicate that cap is not in original position.

A 18" now 22" Hemlock stump bears N.61°E., 68.0 ft. Scribing "S32 BT" visible on remaining partially healed blaze.

A 20" Cedar now 19" stump bears N.69°W., 16.5 ft. scribing "1/4 S32 BT" visible on partially healed blaze.

Set - We replaced monument (previously described) at 1/4 corner position as referenced from bearing trees. Monument set 16" deep and added marks "Reset 1977" to brass cap. Mound stone around monument.

No new accessories. Corner is on steep easterly slope in logged off area.

8/31/77

North 1/4 Sec. 32. T27 1/2 S R 8 W.

Found - A 2 1/2" Iron pipe with brass cap set 12" above ground marked

"1/4 S32
T27 1/2 S R8W
1961

A stump hole bears S.72 1/2°E., 30.4 ft. Remains of tree not found.

A 40" Hemlock stump bears S.36°W., 70.6 ft. with no visible blaze.

A 6" now 8" Yew bears S.36°E., (Rec. S.41°E.) 17.7 ft. scribing

"1/4 S32 BT" visible on partially healed blaze. Ren. #9

Renewal - Stamped "N" on brass cap to read "N 1/4 S32" T27 1/2S R8W 1961.

12/5/77

Vernon "Ray" Tracy
C. S. File No. 54/113

Howard W. Johnstone
For: Rebrg. Lumber
C.S. File No.
55/286

Gary L. Langlitz
Larry E. Monrean
Steve J. Flause
Doug. Co. Surveyors Office
Aug. 31, 1977
C.S. 59/388

R. B. Kimberling
S. J. Flause
Doug. Co. Surveyors Office

Dec: 5, 1977
C.S. 59/42

RE-RENEWED CORNER NO. #11

Jan 78
1-79