

Douglas County Surveyor's Record of  
Government Corners Renewed

T 30

T. S.

R 1

R.W.W.M.

KORE-CHAPMAN CO. EUGENE 21881

209

1/4 Corner for Secs. 29 and 32

Set - Brass cap marked "T30S RLW. W.M. 1/4 S29 S32 RLS 430 1981"  
BT's - 18 D. Fir, I scribed "1/4 S29 BT" bears N.54 1/2°W., 48.5 ft.  
18" D. Fir I scribed "1/4 S32 BT" bears S.5°E., 41.7 ft.

210

1/4 Corner for Secs. 28 and 29

(Ren. #4)

Set - Brass cap marked "T30S RLW WM 1/4 S28 S29 RLS 430 1981"  
BT's - 12" D. Fir BT, I scribed "1/4 S28 BT" bears N.34°E., 19.0 ft.  
10" D. Fir BT, I scribed "1/4 S29 BT" bears N.38 1/2°W., 30.6

211

Section Corner for Sections 20, 21, 28 and 29.

Found - 1967 County Brass cap properly marked. Ren. # 28  
30" D. Fir snag, orig BT scribes visible bears N.62°W., 23.0 ft.  
(Co. rec. N.60°W., 21.8 ft.)  
12" Cedar windfall, orig. BT burnt out face, bears S.2°E., 50.8 ft.  
26" Cedar BT scribes visible bears S.3 1/2°E., 72.2 ft.  
24" Cedar BT scribes visible bears S.53°W., 39.5 ft.  
34" D. stump BT scribes visible bears N.81°W., 68.0 ft.  
14" Madrone BT scribes visible bears N.79°E., 25.6 ft.

New BT - 10" Cedar BT, I scribed "T30S RLW S20 BT" bears N.35°W., 37.7 ft.

1/81

212

1/4 Corner for Section 24 only. (west side)

Found - 1923 US GLO brass cap properly marked lying loose on ground near a 1" cement filled I.P. protruding 8" from the ground leaning north and firmly set. The buried portion of the I.P. is uncovered and the pipe is found to be bent as well as leaning north. The accessories found are measured from the bottom end of the monument pipe.  
1923 16" now a 20" DBH D. Fir bears N.45°E., 48.2 ft. Tree has a well healed single blaze, no scribing visible.  
A 15" now 25" DBH Madrone (laurel) bears S.18°E., 29.7 ft. Tree has faintly visible blaze scar we open and find clear face of old blaze and scribe marks (because of easy rotting nature of this tree species, we do not open to where scribing would be legible).

Because bearings and distances agree to the bottom of the pipe found, and old road work in the area probably disturbed the original positioning, the location of the bottom of the found 1" I.P. is referenced out, the pipe removed from the ground, straightened & the GLO brass cap reattached to the top; This monument then is placed back in the referenced position. Because of likelihood of the GLO brass cap again coming loose ;

WE SET - A DCSO 2 1/2" Brass cap on a 1" by 30" I.P. is placed on the south edge of the above mentioned monument. BC is marked "Douglas County Surveyor" 1/4 S24 RLW 1980. Both monuments are firmly set, the GLO monument now protrudes 8 1/2" and the DCSO monument 7" from the ground.

New BT's - A 31" DBH Cedar bears S.34 1/2°W., 92.8 ft. and is scribed "1/4 S24 CS BT" on a double blaze.  
A 37" DBH D. Fir bears N.21°W., 51.1 ft. and is scribed "1/4 S24 CS BT" on a double blaze.

These new trees are tagged with eCSO BT tags noting corner is for Section 24 only.

213

Witness corner, 1/4 Corner for Sections 5 and 6.

Found - From 1905 resurvey, a red fir, 30" diam. marked as the corner tree is now a 34" diam. approx 4 foot tall rotted fir stump, an open and burned blaze on its west face has the scribing 4 S6 visible, the east face is burned and has a blaze but no scribing is visible.

A 1968 County Brass cap, 2 1/2" on a 1" I.P. protrudes 15" above ground & bears North 2.0 ft. from above corner. Cap marked "County Surveyor T30S RLW 1/4 6 5 1968". Ren. #31

No accessories from orig. 1857 survey are found. These were destroyed in 1905 resurvey.

Bruce Shaner  
PLS #430  
For: U.S. Forest  
Service  
January 1981  
RM 3 - 43

Stephen J. Flause  
Deputy, Doug. Co.  
Surveyors Office  
T. Plouff; B. Stewart  
Began 9/15/80; completed  
3/7/81  
C.S. 61/19

Stephen Flause,  
Deputy, Doug. Co.  
Surveyors Office  
Terrie Plouff  
Karen Mosely  
Feb. 26, 1981  
C.S. 61/19

FO. BC. 9/93  
PESKE M117-62