

Douglas County Surveyor's Record of
Note - Corner lies on a steep south slope in a north-south
Government Corners Renewed

30 T.S. 2 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21991

Mark Smalley,
L.S. #2354
For: Roseburg
Resources Co.
April 1995
M 121-77

1/4 Cor. Secs. 32 & 33 283
Found - 1979 Brass cap mkd: PLS 966 (Ren # 221)
20" madrone N.76°W., 12.5', down & rotten.
24" fir, S.64°E., 8.0', healed.
46" fir, S.85°W., 35.4', healed.
New BTs- 6" fir, N.5°E., 26.9', scribed "1/4 S BT"
10" fir, S.36°W., 14.8', scribed "1/4 S BT"

Douglas County
Surveyor's Office
Randall Smith
Stephen Flause
Oct. 27 1994
C.S. 64/58-5

1/4 Corner for Sections 14 & 15 284
Found - 3 1/4" Brass cap on a 2 1/2" O.D. iron pipe, loosely set,
protrudes 21" above ground. BC/IP leans 18" south of plumb. (1963
BLM)
-Unmarked 10"x10"x6" conglomerate stone found loose along
southwest edge of BC/IP (orig.?)
-Note: Evidence of ground being disturbed in area around
corner position of fd. BC/IP. Does not fit well with
remaining BT/s. We calculate a position for corner based
on remaining BT's. Top of brass cap shows evidence of
being hit.
Accessories Found - (brg. & dist. taken from position determined from
BT's)
-18" now rotted 5 ft. high Madrone staub. No marks visible.
Bears S.49°W., 21.1 ft. (agrees with 1963 BLM) Orig. BT.
-Original southeast Pine now gone.
-13" now 19" dia. D.Fir with a fully healed double blaze,
bears S.19°E., 23.8 ft. (agrees with record) 1963 BLM
-19" now 23" dia. down D.Fir with a fully healed single
blaze. Root hole is large and indefinite. (rec. S72°W.,
38.3 ft.) 1963 BLM
Monument Set - Position of loose BLM BC/IP is referenced with a
5/8" x 32" long iron rod with a DCSO alum cap marked "BO
1 1995". Iron rod protrudes 4" above ground.
-1963 BLM brass cap iron pipe measures 28" long is set at a
point determined from remaining bearing trees. The marks
"RESET 1995 DCSO" are added. BC/IP now protrudes 8" above
ground.
New Accessories -
-9" dia. D.Fir double blazed and scribed "1/4 S14 CS BT"
bears S.74 1/2°E., 19.4 ft. to center of root crown.
-4" dia. D.Fir double blazed and scribed "X BT"
bears S.60°W., 9.4 ft.
-5/8" iron rod with a DCSO alum. cap marked "BO 1 1995"
bears S.8 1/2°E., 6.4 ft.
Note - Corner lies on a steep south slope in a north-south
fence line.

Bruce Shaner,
L.S. #430
For: Rsbg Forest
Products
Clem Berlier
David Snyder
June 1995
M 119-64
C.S. File
63/161-36-B

1/4 Cor. Secs. 31 & 32 285
Found - Broken, decomposed granite stone from which:
24" (rec. 16") D.Fir, O.B.T., now stump, badly rotted, with
scribes "1/4 S" visible, bears S.7°E., 18.5'.
36" D.Fir, O.B.T., now badly rotted root collar & rot only,
bears N.48°W., 35.0'.
Set - I set a 1"x30" I.P. with a 2 1/2" brass cap, mkd:
T30S R2W W.M.
+
S 31 | S 32
RLS 430 1995
8" D.Fir BT, I scribed "1/4 S31 BT" bears S.38°W., 22.6 feet.
8" D.Fir BT, I scribed "1/4 S31 BT" bears N.52°W., 8.8 feet.
8" D.Fir BT, I scribed "1/4 S32 BT" bears S.88°E., 14.2 feet.
12" D.Fir BT, I scribed "1/4 S32 BT" bears N.34°E., 37.0 feet.
6' steel fence post bears North, 1.0 foot.