

Douglas County Surveyor's Record of  
Government Corners Renewed

30 T. S. 4 R. W. W. M.

- ✓ N. E. CORNER OF D.L.C. # 46. 29  
Set Iron Pipe from O.B.T. FOUND SEE M 42-1  
A 24" Black Oak S.15°E., 9.2 ft. O.B.T.  
A 20" Black Oak N. 7°E., 44.0 ft.
- ✓ N. E. CORNER OF D.L.C. # 47. 30  
Set seasoned Oak Post from stamp hole of O.B.T. Marked  
A 24" Black Oak S.48°E., 17.8 ft.  
A 12" Laurel S.65°W., 38.0 ft.
- ✓ CORNER BETWEEN 10 and 15. 31  
Reset from two Original Posts, one rotted. Drove  
an Iron pipe in state. Re-surveyed  
A 20" White Oak of O.B.T.
- ✓ BUSINESS CORNER FOR S.W. EXTERIOR CORNER OF D.L.C. 47. 32  
Reset from two Original Posts, one rotted. Together with  
A 8" Fir S.12°E., 21.7 ft.  
A 18" Laurel S.12°E., 21.7 ft.
- ✓ CORNER OF D.L.C. 47. 33  
Reestablished by running from West corner to West and  
from S.W. corner of Claim 48 to North, according to distances  
from resurvey of Claim 47. Set Iron wagon axle for corner  
at edge of county road. Marked  
A 14" White Oak S.73°E., 223.9 ft.
- ✓ S.W. CORNER OF D.L.C. NO. 48. 34  
Found Iron Bar buried 18" under Road pointed out as  
corner. All B.T.'s gone. Location checks with deed description  
for a witnessed corner. A 20" White Oak N.18°E., 38.6 ft.  
Buried Black Rock N.78°W., 21.8 ft.
- ✓ S.E. CORNER OF D.L.C. NO. 48 (Andrew Thomas). 35  
I renewed this corner by setting an Iron Pipe 1 1/2 x 40"  
from which  
A Black Oak 14" dia. bears S.69°45'W., 67.4 ft.  
A White Oak 16" dia. bears North 74.9 ft.  
Corner was reset from Theils bearing tree which was alive  
and bearing scribe marks. Tree badly burned.
- ✓ SECTION CORNER COMMON TO SECTIONS 6 and 7. 36  
I identify the location of this corner by two old bearing  
trees as follows, SEE #38  
A 20" Fir marked 1/2 S. B.T. N.29°W., 17 lks. The bearing  
of this tree as given in the government field notes  
is N.15°W.,  
A 10" Black Oak marked 1/2 S. B.T. S.15°W., 80 lks.  
I renewed this corner by driving a 1/2" x 1" x 24" Iron  
Bar 20" in the ground and a White Oak Post 3" x 36" in  
the ground.  
As old Black Oak B.T. is badly rotted I marked  
An 18" Fir S.6°W., 21 ft. 1/2 S.7 C.S.B.T.
- ✓ SECTION CORNER COMMON TO SECTIONS 6 and 7 T.30-4 and 37  
I identify the location of this corner by four B.T.'s which  
with one exception check with the government field notes.  
The only exception is that a fir was recorded as S.37°E. and  
I found it to be S.22°E.  
For this corner I set a 1/2" x 2" x 20" Iron bar 18" in  
the ground and an Oak Post 4" x 4" x 6".
- ✓ SEC. COR. SECS. 6-7 38  
1/2" x 1" x 20" bar could not be found. SEE #36  
1/2" x 34" copperweld rod, 3" out of ground set for corner from two old  
B.T.'s and original post.  
10" B. Oak S 15° W 52.8 ft. and  
12" Fir (much larger now) N 15° W 11.2 ft.

G. G. Stewart  
Wit.  
H. A. Hill  
4/6/22.  
W. S. Cress  
4/7/22.

G. G. Stewart D.C.S.  
Dec. 29, 1922  
Wit.  
Montgomery, Morron  
Moore, Beals.

M 2-9  
Vol. 3 P. 136

J. W. Cole  
Wit.  
B. E. Irvine  
J. R. Chaney  
P. L. Beals  
J. Sinton  
Feb. 6, 1924

Ben E. Irvine  
Wit.  
L. H. Smick  
Huron Clough  
J. L. Worthington  
Feb. 5 to 7, 1927

T. R. Eslinger - Surveyor  
February 2, 1951

see C.S. 7/6

C.S. 3/63  
Vol. 3 P. 273

C.S. 40/299

RE-RENEWED, SEE CORNER NO. 261

RE-RENEWED, SEE CORNER NO. 191

RE-RENEWED, SEE CORNER NO. #247

RE-RENEWED, SEE CORNER NO. 249

RE-RENEWED, SEE CORNER NO. 248:66

RE-RENEWED, SEE CORNER NO. #68

RE-RENEWED, SEE CORNER NO. 229

RE-RENEWED, SEE CORNER NO. 113

RE-RENEWED, SEE CORNER NO. 229