

Douglas County Surveyor's Record of
Government Corners Renewed

T 30 T. S. R 7 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91801

123

B. Rogers
Jan. 1974
M 49-53

Center 1/4 Corner for Section 2
Set - 5/8" Iron rod. 5.4 ft. South of E-W fence.

H. Johnstone
For: Rsbg. Lbr.
Jan. 30, 1981
M 86-77

Corner report only - - - Found 5/8" I.R. 6 ft. south of E/W. fence line
No BT's.

FD OK 4/96 R. BROWN M 123-72

124

Romanso E. Ware
For Dean Sanders
July 1975
M 57 - 52

Section corner for Secs. 22, 23, 26 and 27.
SURVEY REVISED - Brass cap set April 1975 on Survey map # M 57 - 3 Ren.#115
was replaced with a 1 1/4" I. pipe July 1975 (M 57 - 52)
Brass cap set at proper section corner bears S.50°40'35"W., 107.19 ft.
from 1 1/4" I. pipe. (corner double proportioned)
The bearing trees described in Ren: #115 are now from the Iron pipe and
described as follows:
8" fir scribed "S27 BT" bears S.70°W., 147.7 ft.
7" fir scribed "S22 BT" bears N.57°W., 80.6 ft.
30" Oak (fallen over) old face & chop marks grown over bears N.28°W.,
132.0 ft.
24" cedar scribed "S23 BT" bears N.41°E., 153.2 ft.
13" W. oak scribed "S26 BT" bears S.65.5°E., 59.1 ft.

(SEE C.S. 61/33 FOR CURRENT STATUS OF THIS CORNER PER BLM) 7/75

125

Gregory Quibell,
Deputy, Doug. Co.
Surveyors Office
John Powell - Randy Smith
January 28, 1983
C.S. 62/7

Township corner, Sec. 1; and Sec. 36, T.29-7; Sec. 31, T.29-6; Sec. 6 T.30-6
Found - 1962 Douglas Co. Surveyors brass cap properly marked and firmly
set. Ren. #29
1968 BLM brass cap per resurvey properly marked and firmly set
with what appears to be the original corner stone buried
alongside. Doug. Co. brass cap bears S.23 1/2°E., 1.65 ft. from
BLM cap.
Found all accessories as described in 1968 resurvey and 1982 Lloyd
Smith survey. (M 93-45)

My measurements to the two remaining original bearing trees from each of the
brass caps, plus faint notches on all four edges of the found stone cause
me to accept the position of the BLM brass cap as the proper corner location.
I then cut the DCSO brass cap off and drive a yellow nylon cap inside the
remaining 1" iron pipe. Cap marked Doug. Co. Surveyor.

1/28/83

126

Howard Johnstone
For: Roseburg Lbr.
February 10, 1983
M 93 - 55

1/4 Corner for Section 31; and Sec. 6 of T.31-7
Found - 1918 GLO brass cap and iron pipe.
24" W. fir, N.60°E., 50.2 ft.
20" W. fir, S.41°W., 20.5 ft.
New BTs - 5" Yewood, S.62°E., 22.7 ft.
10" W. fir, N.46°E., 22.8 ft.

2/10/83

127

Howard Johnstone
L.S. #498 For:
Roseburg Lbr.
C.S. 58/290
April 2, 1984

Section corner for Secs. 17, 16, 20 and 21.
Found - 34" D. fir, N.10°W., 29.5 ft., now a stump. (OBT)
12" D. fir, N.64°E., 11.0 ft., now a stump. Ren. #89
16" D. fir, S.37°E., 12.8 ft., stump hole. "
10" D. fir, N.39°W., 30.0 ft., stump. "
17" D. fir, S.81°W., 27.0 ft. Stump with part of scribe visible.
All stumps painted yellow and tagged with yellow loction marker tags.
Brass cap not found - recent logging has destroyed this corner and BTs.
Set - 48" x 5/8" Iron rod with alum. cap marked "T30S R7W 1984 16 17
20 21 RLS 498".
New BT - 29" D. fir, S.18°E., 29.5 ft.
No other trees within a reasonable distance.

4/2/84

H. Johnstone
For: Rsbg. Lbr.
June 11, 1984
C.S. 58/296

NOTE: BEARING TREE ADDED TO ABOVE CORNER, JUNE 11, 1984
8" D. fir, N.43°W., 277.5 ft. (No other trees closer in
Section 20)
Corner about 200 ft. east of road. Section 16 and 20 clearcut.