

Douglas County Surveyor's Record of
Government Corners Renewed

31 T. S. 8 R. W. W. M.

MOKE-CHAPMAN CO., EUGENE, ORE. 91881

James W. Byron, Deputy
M. Godfrey
S. A. Bilow
August, 1958
C. S. File No. 49/109

1/4 Section Corner to Sections 21 & 28.
Found - Orig. 16", now 16" R. Fir, previously opened. Shows good scribing "1/4" N.62°E. 10.6 ft.
Orig. S. E. BT., shows good scars. I do not open.
Checks bearing & distance.
Set Brass Cap at Corner Mkd: 1/4 S21 T31S R8W County Surveyor's Office, 1958.
New BT's: I rescribe Orig. N.62°E. 10.6 ft. BT. 1/4 S21 CS BT.
10" R. Fir bears S.78°E. 10.4 ft. scribed 1/4 S23 CS BT.

13

FD. OK
6/81
H. J. Schmitt
N 87-74

1/4 Section Corner to Sections 20 & 29.
Found - Orig. 12", now 24" Fir S.12°E. 14.5 ft., previously opened, shows good scribing "1/4 S".
No trace of Original N. E. BT.
Set Brass Cap at Corner Mkd: 1/4 S20 T31S R8W County Surveyor's Office, 1958.
New BT's: 12" Cedar bears N.46°E. 45.0 ft. scribed 1/4 S20 CS BT.
I rescribe Orig. S. E. BT. 1/4 S29 CS BT.

14

FD. OK.
by S. P. Ness
DEC. 1981
M 89-65
98

Lorne Swearingen
Wit: Robert Harris &
Milner Larson
Feb. 18, 1960
C. S. File No. 51/68

1/4 Corner common to Section 31, T31S R8W, & Sec. 6, T32S R8W.
This corner was found to be in poor condition.
The original bearing tree in Sec. 31 was felled in a clear cut logging operation. This tree had been barked scribed and the evidence of scribing visible before falling. The original bearing tree in Sec. 6 remains standing but is a snag.
The original corner called for a stone, not found.
I set a 1" (inner diam.) Iron Pipe driven 18" into the ground for the quarter corner for Sec. 31, T31S R8W, & Sec. 6, T32S R8W.
Since the area to the north has been clear cut and no trees available to scribe, a 40" D. Fir S.58°E. 39.7 ft. was referenced and scribed S 6 1/4 S, B.T.
Bearing tree was referenced with a compass and chain, magnetic declination used was 19 1/2°E

15

54

Robert Dollar Co.
By Lorne Swearingen
April 15, 1960
C.S. File No. 51/68

1/4 Corner common to Section 31, 31-S 8-W, & Sec. 36, 31-S 9-W.
Found to be in poor condition. The Orig. BT. in Sec. 31, T31S, R8W was bark scribed & had been burned until the scribing was almost invisible. The BT. in Sec. 36, T31S, R9W, W.M. was rotted away & only the stump hole remaining.
Set a 7/8" Hex drill steel 20" in the ground for the quarter corner:
6" D. Fir N.61°W. 26.1 ft. was ref. & scribed S 36 1/4 S 4186 BT.
36" D. Fir N.42°S. 15.8 ft. (old BT) ref. & scribed 1/4 S 4186 BT.

16

53

47

O
V
E
R