

Douglas County Surveyor's Record of
Government Corners Renewed

31

T. S.

9

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Wallace D. Owen
For Robert Dollar Co.
Wit: L. Swearingen
R. Harris
Feb. 1958
C. S. File No. 42/329

N. W. Corner of Section 36.

The orig. BT's. were:

12" Fir, N.23°W., 20 lks.

8" Maple, N.80°E. 26 lks.

10" Fir S.30°E. 11 lks.

Only rotten stubs were left of the three orig. Fir BT's., but scribing was still visible. The Maple BT. had disappeared but a clump of sucker maples was growing in the spot of call.

New Bearing Trees: 30" Fir, N.72 $\frac{3}{4}$ °E. 44.9 ft. scribed S25 T31S R9W LS424 BT.

30" Fir S.70°E. 66.8 ft. scribed S36 T31S R9W LS424 BT.

40" Fir S.14 $\frac{1}{2}$ °W. 45.2 ft. scribed S35 T31S R9W LS424 BT.

3"x3"x4" 6" Fir N.42°W. 14.8 ft. scribed S26 T31S R9W LS424 BT.

Maple Post Set and a $\frac{1}{2}$ " Iron Rod was driven.

CORNER NO. 78

1

Wallace D. Owen
Wit: Robert Harris
For Robert Dollar Co.
Feb. 2, 1959
C.S. File #42/424

$\frac{1}{4}$ Corner common to Sections 25 & 26.

Found in poor condition and new witness trees were scribed.

The West bearing tree had fallen over, the East bearing tree

had fallen over and rotted out but found the Stone

marked $\frac{1}{4}$ for the corner.

Drove a $\frac{3}{4}$ " Pipe from which:

42" D. Fir scribed $\frac{1}{4}$ S 26 T31S R9W RS424 B.T. bears S.66 $\frac{1}{2}$ °W. 3.8 ft.

40" D. Fir scribed S25 $\frac{1}{4}$ S RS424 B.T. bears N.19 $\frac{1}{2}$ °E. 18.0 ft.

Used compass declination 19 $\frac{1}{2}$ ° & chain for referencing bearing Trees.

RE-RENEWED CORNER NO. #28

2

C.S. Lehmanowsky,
Engineer
Filed May 4, 1959
C.S. File No. 51/18

$\frac{1}{4}$ Corner between Sections 7 & 18.

Set a 4" sq. Post for this Corner, from Orig. BT's.

12" Fir S.80°W. 40 lks. is now a Snag & unlikely to withstand logging operation.

The notes for the Orig. 12" Fir N.30°E. 67 lks., should read Fir 12" N.12°E., 67 lks.

New BT: 36" Fir S.64°E. 19.0 ft., $\frac{1}{4}$ S. B.T.

April 20, 1959

RE-RENEWED CORNER NO. #83

3

Wallace Owen
For The Robert Dollar Co.
Wit: Robert Harris
Lorne Swearingen
Sept. 18, 1959
C. S. File No. 42/424

$\frac{1}{4}$ Corner common to Section 22 and 27.

Found in poor condition. The South BT, 8" Fir bears S.15°W, 14 lks, had fallen over and rotted but scribing was still visible. The point of a Yew Post was found, as described, from the bearing tree. The North Bearing Tree, an 8" W. Fir bears N.89°W. 17 lks. had completely disappeared.

The Corner was marked with 1" Rod driven 18" into the ground.

38" D. Fir N.39 $\frac{1}{2}$ °E. 14 ft. was referenced and scribed

$\frac{1}{4}$ S 22, RS 424, BT.

24" D. Fir S.18 $\frac{1}{2}$ °W. 20.9 ft., was referenced & scribed

$\frac{1}{4}$ S 27, RS 424, BT.

Bearing trees were referenced with a compass & chain.

Magnetic declination used was 19 $\frac{1}{2}$ °E.

RE-RENEWED CORNER NO. #47

4

Robert Dollar Co.
By Lorne Swearingen
April 15, 1960
C. S. File
No. 51/68

$\frac{1}{4}$ Cor. common to Sec. 36, T31S R9W, & Sec. 31, T31S R9W. Found to be in poor condition. The orig. BT. in Sec. 31 was bark scribed & had been burned until the scribing was almost invisible.

The BT. in Sec. 36, was rotted away & only the stump hole remains.

I set a 7/8" Hex drill steel 20" in the ground for the $\frac{1}{4}$ corner.:

6" D. Fir N.61°W. 26.1 ft. was ref. & scribed S 36 $\frac{1}{4}$ S 4186 BT.

36" D. Fir N.42°S. 15.8 ft. (old BT) ref. scribed $\frac{1}{4}$ S 4186 BT.

RE-RENEWED CORNER NO. #53

5

Lorne Swearingen
Robert Dollar Co.
May, 1960
C.S. File
51/68

Section Corner common to Sections 4 - 3 - 9 - 10.

All Original BT's. were found and in good condition.

I set a 7/8" x 30" Hex drill steel, driven 20" in the ground.

RE-RENEWED CORNER NO. #53

6

$\frac{1}{4}$ Corner common to Sections 4 and 3.

Both Original BT's. were found with scribing visible.

I set a 7/8" x 30" Hex drill steel, driven 20" in the ground for the corner.

FD OK Jerry Estabrook
6/2005
4148-32