

Douglas County Surveyor's Record of
Government Corners Renewed

T. 32 S. T. S. R. 3 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97101

150

See CS
68/57-1-A/B
For USFS
Narrative
concerning
1/4 1/4 Center
1/4 Sec. 14

1/4 Corner to Section 11 and Section 14.
Desc. of corner evidence found: I made a tie to the location of the corner from traverse I made on exterior boundary of Section. 4 ft. S. & 2 ft. E. of tie location, I found a stone set in the ground, a granite stone, 18"x15"x4", 12" in the ground. The granite showed signs of weathering & any markings that may have been on the stone are gone. There is no trace of the original BT's. except 2 large stools in the approx. location where the S.E. BT. stood.

Due to the lack of evidence, I establish the location of the corner by prop. measurement. At this location I set a 2"x30" galv. iron pipe, flared at the bottom, with a 3" bronze cap welded to the top.

I stamped this cap _____ T32S R3W
1/4 S 11
S 14
RLS 544

FD. OK
11/17/81
L. Hazzard
C.S. 6/29

From the pipe monument, I establish new BT's. as follows: 1971
An 18" Pine bears S. 83 1/2° E. 62.2 ft. scribed "1/4 S14 BT".
A 7" Madrone bears N. 29° W. 10.7 ft. scribed 1/4 S11 BT.
A 6" Steel Fencepost with sign 54-4 attached bears South 5 ft.

United States of America (Forest Service)
By Don E. Garrett 9/7/71
C. S. File 55/215 Map File M 43 - 53

151

1/4 Corner to Section 13 and Section 14.
Desc. of cor. evidence found: I made tie to cor. from traverse of E. line of Sec. 14. In clear-cut unit, approx. 250 N. of road & S. of small creek, I found a 21" Fir stump. I chopped out old scribing & found 1/4 scribed clearly in stump. I found iron stone in approx. location of orig. 1/4 corner. Stone had been knocked 2 ft. N. of orig. position by logging operations & was lying on its side. The stone had 1/4 clearly marked on its side. 8" Maple BT was destroyed by logging operations.

I reestablished the location of the corner from the stump of the orig. BT., S. 64° W. 32 lks. At this location, I set a 2"x30" galv. Iron pipe, flared at the bottom, with a 3" bronze cap welded to the top. I placed the orig. stone monument described above, in hole, alongside iron pipe.

I stamped this cap _____ T32S R3W
1/4 S 14 S 13
RLS 544

From the pipe monument, the Orig. BT. is: 1971
A 16" Red Fir, now 21" stump, bears N. 64° E. 32 lks.
I also established new BT stumps, as follows:
25" Fir Stump bears N. 88° W. 54.9 ft. scribed 1/4 S14 BT.
40" Fir Stump bears N. 23 1/2° E. 73.6 ft. scribed 1/4 S13 BT.
A 6' Steel Fencepost with sign 54-4 attached, bears North 5 ft.

152

Center 1/4 Corner of Section 14.
Descs. of monument & accessories I established to perpetuate the location of this corner.
After location of the found 1/4 corners of Section 14 were established by traverse, I located the center 1/4 corner of Section 14 at the intersection of the E-W & N-S centerlines. At this location I set a 2" x 30" galv. Iron pipe, flared at the bottom, with a 3" bronze cap welded to the top.

I stamped this cap _____ T32S R3W
Cntr 1/4 S14
Cor.
RLS 544

I established new BT's. as follows: 1971
A 10" W. Fir bears S. 62 1/2° W. 8.9 ft. marked C 1/4 S14 BT.
A 9" W. Fir bears S. 80° W. 19.0 ft. marked C 1/4 S14 BT.

Sept. 7, 1971

RENEWED, SEE CORNER NO #206