

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 32 S. T. S. R. 9 W. R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORG. 21881

Robert Dollar  
Co.  
by L. V.  
Swearingen  
May 1963  
C. S. File  
No. 51/68

Section Corner common to Sections 4, 3, 10 and 9.  
Corner found to be in poor shape. The Orig. 36" Fir S. 66° E. 47 lks.  
has been blown over and logged. After the tree was cut into logs,  
the stump tipped back upright leaving a stump approx. 10' tall.  
Orig. bark scribing is plainly visible on this stump. The Original  
50" Fir N. 45° W. 111 lks. is still standing but will probably be cut in  
the near future. The Orig. bark scribing on this tree has practically  
disappeared. The other two original BT's. are gone.  
I marked the corner with a 7/8" x 30" Hexdrill Steel, driven 20" in the  
ground. I referenced two new Bearing Trees:  
8" I. Cedar S. 57° E. 66.5 ft., scribed S9 R4186 BT.  
4" Tan Oak N. 29 1/2° E. 15.0 ft. scribed S3 R4186 BT.

*R6W*  
*When Tree changed*  
*SEE #190*  
*732-64*

1

John M.  
Powell &  
Crew  
12-21-66  
C. S. File  
No.  
54/36

Reset Corner to R9W 

S 31	R8W
S 1	T 31 S
S 6	T 32 S

  
Found - Brass Cap at Corner but out of the ground.  
16", now 28" D. Fir, S. 10° E. 43.6 ft., shows good scar.  
30" D. Fir, S. 10° W. 54.0 ft. (not 46.2 ft.) shows good scar.  
60", now 55" D. Fir, N. 14° W. 19.1 ft., shows bark scribing.  
Reset - G.L.O. 1917 Brass Cap at proper position.  
All BT's tagged and all right.  
This corner lies south of Road 50.0 ft. in part of fill.

2

John M. Powell  
Frank Jones & Joe Brady  
March, 1967  
C. S. File No. 54/32

Sec. Corner to Sections 4 and 3 only, T32S-R9W.  
Found - Brass Cap Mkd: U.S. Gen. Land Office  

S 4	S 3	T32S R9W
1917		

  
20" D. Fir S. 81° W. 55.4 ft., this stump washed out.  
20" D. Fir Snag S. 70° E. 29.0 ft., shows good scar.  
New BT's: 5" D. Fir S. 45° W. 5.6 ft. mkd. S 4 CS BT.  
8" D. Fir N. 37° W. 37.6 ft. mkd. T31S R9W S34 CS BT.  
No other trees available.  
Note - This corner lies West of A. P. 141.2 ft. (See below)

3

Angle Point, T. 31S., R. 9W. and T32S. R. 9W.  
Found - Brass Cap Mkd: U.S. Gen. Land Office  

A.P.	T31S	R9W
1917	T32S	

  
60" D. Fir, now Stump, N. 61° E. 30.4 ft., opened for scribe, "BT".  
24" D. Fir, now Snag, S. 76° W. 16.5 ft., shows scar.  
New BT's: 8" Yew wood S. 61° W. 77.8 ft. mkd. "A P CS BT."  
9" D. Fir N. 30° W. 59.7 ft. mkd. "A P CSET".  
Note - Logging Road bears North 65.0 ft. Also, 141.2 ft. East of  
., See Ren. #3, above.

4

Section Corner to Sections 33 and 34 only, T 31 - 9 W.  
Found - GLO Brass Cap at Cor. Mkd: properly in 1917.  
Brass Cap badly bent and loose.  
Reset Brass Cap and tried to straighten.  
30", now 28" D. Fir, N. 8° E. 13.2 ft., shows goodface.  
24", now 28" D. Fir, N. 20° W. 61.4 ft., shows good face.  
Reblzd. & Rescrbd: 28" D. Fir N. 8° E. 13.2 ft. scribed T31S R9W S34 CS BT.

5

1/4 Corner to Section 36 only, T 31 - 9 W.  
Found - 10" D. Fir Corner Tree, now 16", shows good scar on North face.  
14", now 17" Maple, N. 8° W. 37.6 ft., shows scar.  
7", now 7" Maple, N. 55 1/2° E. 80.2 ft. (Record 83.2') rotten  
scribing visible "1/4 S".  
New BT: 7" Laurel N. 54 1/2° E. 81.8 ft. mkd. "1/4 S36 CS BT".  
Note - This corner lies in very rocky area on north slope, approx.  
110 ft. East of Creek.

6