

Re-establishment of North 1/4 Corner, Section
26, Township 21 South, Range 4 West, W. M.

At one-half distance between Northeast section corner and Northwest section corner, said Section 26, said Township and Range, set 4"x4"x3' fir stake from which a 14" Douglas Fir bears South $12\frac{1}{2}^{\circ}$ East 10.0 feet, marked $\frac{1}{4}$ SBT. No other trees available.

Re-establishment of South 1/4 Corner, Section
26, Township 21 South, Range 4 West, W. M.

At one-half distance between Southeast section corner and Southwest section corner, said Section 26, said Township and Range, set 2" iron pipe from which 14" incense cedar bears north $50\frac{1}{2}^{\circ}$ east 35.0 feet east and a 24" incense cedar bears south 80° west 110.6 feet; both trees marked $\frac{1}{4}$ SBT. This corner comes at a point near where there are old cruiser marks on a 12" incense cedar, now dead and down; this old incense cedar also shows slight evidence of scribing marks in the lower face, but original field notes do not call for incense cedar.

Note: These two 1/4 corners re-established in course of survey for W. A. Woodard Lumber Company filed this date.

Gilbert A. Gardner
Gilbert A. Gardner, Registered
Oregon Land Surveyor No. 276.
Present when 1/4 corners were
marked and during course of
survey: Robert Barta.
February 16, 1956.

Nov. 20, 1964 *L.*

Fine Printing Anytime at
M·M PRINTERS and LITHOGRAPHERS
629 S. E. Cass Ave.
ROSEBURG, ORE.
Phone 673-8591

RENEWAL # 66 $\frac{22}{27} \frac{23}{26}$
T 21354W

FENCE COR. FD. BUT I DO NOT
BELIEVE IT IS SEC. COR. —
CALLS DO NOT FIT & NO
EVIDENCE OF B.T.'S FD.

REN. # 25 ($\frac{1}{4} \frac{S23}{S26}$) IS BASED
ON FENCE COR. ABOVE & SET
BY PROPORTION. — IF # 66 IS
NO GOOD, NEITHER IS # 25

FRED SAYS FLAG
THESE IN REN. BOOK AS
QUESTIONABLE.

Mills

C.S. FILE 42/131