

T. 24S., R. 2W.

Renewal of  $\frac{1}{4}$  S 22 & 23

Before logging the original stone corner could not be found. There was evidence of an old rotted stump in the correct position of bearing tree for sec. 22. The bearing tree for sec. 23 was a dead snag with scribing visible.

After logging in section 22 only the B. T. for section 23 remains.

At the true point of the corner, I drove a  $1\frac{1}{2}$ " iron pipe 36" long, 24" in the ground, from which;

A hemlock 10" in diam. bears N.  $57^{\circ}$ E. 3.2 ft.

marked  $\frac{1}{4}$ S 23 253 B. T.

A hemlock 12" in diam. bears N.  $20^{\circ}$ W. 22.5 ft.

marked  $\frac{1}{4}$ S 22 253 B. T.

Sept. 16, 1957



FILED  
RECEIVED

OCT 8 1957

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

C. S. File No. 42/306-2