

T. 25S., R. 2W., W.M.

Renewal of $\frac{1}{4}$ section corner 7 & 8

After logging in section 7 I found the original corner stone dislodged. Both original bearing trees are in good condition, the Yew now 11" in diam., the hemlock now 24".

At the true point of the corner I drove a $1\frac{1}{2}$ " iron pipe 36" long, 24" in the ground and placed the original corner stone at its east edge.

Oct. 17, 1957



FILED
RECEIVED

OCT 22 1957

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

200540

C. S. File No. 42/308²