

T. 25S., R. 2W.

Renewal of section corner 13, 14, 23, & 24

Before logging only the N. W. bearing tree remained alive, the S. E. bearing was a dead snag with scribing visible, the other two bearing trees were not found.

After logging in sections 13, 23, & 24 only the N. W. bearing tree remains.

At the true point of the corner I drove a  $1\frac{1}{2}$ " iron pipe 36" long 18" in the ground, from which;

A fir 12" in diam. bears N.  $32^{\circ}$ E. 25.4 ft.

marked S 13 253 B. T.

A fir 14" in diam. bears S.  $8^{\circ}$ E. 16.0 ft.

marked S 24 253 B..T.

A fir 9" in diam. bears S.  $54^{\circ}$ W. 19.0 ft.

marked S 23 253 B. T.

A fir 15" in diam. bears N.  $12^{\circ}$ W. 15 links

(original B. T. not re-marked)

Sept. 18, 1957



FILED  
RECEIVED

OCT 10 1957

COUNTY SURVEYOR  
DOUGLAS COUNTY, OREGON

600400

C. S. File No. 42/308-9