

T. 25S., R. 1W. & T. 25S., R. 2W.

Renewal of section corner $\frac{13}{24}$ | 19

At this corner I found the iron pipe with steel cap set in my survey of 1950. The bearing tree for section 13 has been cut. The stump still shows the old faces, but all scribing has burned away. The B. T. for section 24 is up-rooted and badly burned. This area has burned extensively and no green trees remain within a reasonable distance.

From my original I. P. corner;

A fir stump 30" in diam. bears N. 36° W. 21.2 ft.

marked T. 25S. R. 2W. S 13 253 B. T.

(My original B. T. re-marked)

A dead fir 40" in diam. bears S $9\frac{1}{2}^{\circ}$ W. 64.8 ft.

marked T. 25S. R. 2W. S 24 253 B. T.

Sept. 20, 1957



FILED
RECEIVED

OCT 10 1957

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

700400 | 100347

C. S. File No. 42/308-12