

Corner Renewal  
1/4 Sec. Cor. between Secs. 23 and  
26, T30S, R8W, W.M.

The 12" diam. Fir scribed 1/4 S on  
North face for the 1/4 Cor was  
found but is now a snag. The 46"  
diam. Fir BT is a snag and scribe  
near obliteration due to fire. The  
8" diam. Fir BT is gone.

Using the 12" diam. Fir snag scribed  
1/4 S on North face as corner I scribe,  
in the wood, two new B.T.s as below:

A 27" diam. Douglas Fir that lies  
N01°30'E, 49.7 ft. from the Cor  
marked 1/4 S BT S23.

A 23" diam. Douglas Fir that lies  
S50°00'W, 96.1 ft. from the Cor  
marked 1/4 S BT S26.

May 7, 1958



C. S. File No. 42/354