

(T.28-8)

RENEW $\frac{1}{4}$ COR. 35/36 T275 R3W

FOUND - BOTH OF BOYERS RENEWED & TO
 36" B.O. NOW STUMP 557° W 420'
 SHOW ROTTED FACE. NO SCRIBING FOUND
 THE "NOW 22° W. 9 573° 30' E 108"
 HAS ROTTED FACE WITH FAINT SCRIBE
 MKS "B 4". ALSO FIND WHAT I BELIEVE
 TO BE THE ORIG. 556° E. 931.1' BT.
 CHECKS BEARING & DIST AND SHOWS OLD
 FACE - ROTTED NO SCRIBING FD.
 BOYERS & TO. CHECK BEARINGS & DIST.
 I CANNOT FIND BOYERS $\frac{1}{4}$ " I.P.

SET BRASS CAP AT COR. MKD,
 $\frac{1}{4}$ 35/36 T275 R3W COUNTY SURVEYORS
 OFFICE 1957

I BLAZE & SCRIBE 36" B.O. STUMP
 557° W 420' $\frac{1}{4}$ S 35° CS BT.
 10" FORKED CEDAR 526 $\frac{1}{4}$ ° E 614'
 SCRIBED $\frac{1}{4}$ S 36° CS BT.
 11" R. FIR 387° E 96.7'
 SCRIBED $\frac{1}{4}$ S 36° CS BT.



NOTE:

UPON INVESTIGATION - I FIND
 THIS CORNER TO BE ERRONEOUSLY
 MARKED - SHOULD BE T.28-8
 PROPER RECORDING HAS BEEN
 MADE.

SEPT. 19-57
 J. B.
 M. G.
 J. B.

9/13/1984 V. Laugen

#182 T.28-8

corrected ✓ ✓

C. S. File No. 49/5-20