

Renewal #106 . 22/23 T29S R1W

Found

Part of Brass cap out of ground MKD
County Surveyors office

T29S R1W

522/523

1956

PN Bearing Trees are gone (Woods
disposed of)

SW cor of House N 3 E 87 $\frac{1}{2}$ (PL N 10 E 90 $\frac{1}{2}$)

Porch may have been added -

However remainder of Brass cap is

still firmly in ground

Renewal

Set New Brass cap at the same point of
1956 cap - MKD same as above (1971)

New Bearing Tree

1 1/2" Apple

Scribed 45 23 CS BT

S 69 E

11 $\frac{1}{2}$

NE cor of Barn

S 58 W

81 $\frac{1}{2}$

SW cor House (Porch) N 3 E

87 $\frac{1}{2}$

O.K.
J.W.B.

10-19-71
J.W.B.
MKD

#241

C. S. File No. 49/67-44

DIETZEN NO. 385-6