

14113
REVIEW 23124 T 245 R6W

FOUND - ROCK AT CORNER AS RECORDED
BY FIREAR AND I FIND FIREAR'S BTS
THUS 10' NOW 30' FR WEST 73.3'
SHOWS FAULT SCAR I DO NOT OPEN
10' NOW 24' FIRE STUMP SHOWS SCAR I
DO NOT OPEN NORTH 55.4'
6" NOW 14' FR 519' OF 25.1' NORTH
SIDE OF TREE BARK BURNED NO
SCRIBING TO.

I FIND ORIG. 14" NOW 36" W. OAK
312' E 77.9' PARTLY OPENED
FACE. SHOWS GOOD SCRIBING "T"
ORIG. 17" NOW 32" DEAD W. OAK
315' W 61.6' SHOWS GOOD SCAR
I DO NOT OPEN
ORIG. NW BT GONE ORIG. NE BT
NOW DOWN

SET BRASS CAP AT CORNER MKD.

523/523 T 245 R6W COUNTY
523/524 SURVEYORS OFFICE 1954

NEW BTS
14' R. FIR BEARS SOUTH 13.0'

SCRIBED 523 T 245 R6W C.S.BT

6" R. FIR BEAR N 74° E 162'

SCRIBED 523 C.S.BT

26" B. OAK BEARS S 23° E 44.7'

SCRIBED 524 T 245 R6W C.S.BT

30' R. FIR BEARS N 85° W 73.3'

SCRIBED 524 T 245 R6W C.S.BT

FILED
RECEIVED

AUG 26 1958

COUNTY SURVEYOR

C.S. File No. 19/83-19

DIETZEN NO. 388-6