

Dear Sir,

I found the following corners and drove 1" iron pipes at them.

T. 31 S., R. 5 W.

1/4 Cor. bet. 4 + 5

26" Fir N. 26° W. 7.9 ft. good. ✓

50" Cedar S. 65° W. 36.1 good.

1/4 Cor. bet. 4 + 9

40" Fir N. 65° W. 13.9 ft. good. ✓

43" Fir N. 39° E. 19.8 ft. good.

Ran South bet. 4 + 5 found Witness
Corner gone.

Ran West bet. 4 + 9 found Witness
Corner gone

Ran the two lines together for
measurements but did not
establish cor to 4-5-8 + 9.

Geo. J. Wurdnoth
Deputy,

C. S. File No. 49/92-3