

RENEW 1/4 COR 3 1/2 T 245 R 1/2 V

FOUND - ORIG. 36" STUMPS SHOULD HAVE BEEN
2 1/2" DIA W 30" FIR STUMP N 55° W 28 1/2'
I FOUND A FINE GOOD SCRIBING "B"
CHECKS FOR RING COUNT. I FIND
TRACES OF ROTTEN STUMP THAT
CHECKS BEARING & DIST. FOR S E BT.

SET BRASS CAP AT CORNER, MWD
1/4 S 3 1/2 T 245 R 1/2 V COUNTY
SURVEYORS OFFICE 1958.

NEW BT -
8' CEDAR BEARS S 62° E 112'
SCRIBED 1/2 S 1 C S BT

12" R FIR BEARS N 24° W 70 S'
SCRIBED 1/2 S 3 C S BT

VAR. 20 1/2°

SEPT. 25-58

H.B.
M.G.
W.B.



RENEW 1/4 COR 4 T 255 R 1/2 V

FOUND - BOTH BT'S & ROD AT COR. AS
RECORDED BY BOYER. THE NE
BT NOW STUMP SHOWS BARK SCRIBING
THE SW BT ALSO SHOWS BARK SCRIBING
"1/2 S 9"

NEW BT -
10' R FIR BEARS N 56° W 214'
SCRIBED 1/2 S 4 C S BT



C. S. File No. 49/100-^A

DIETRICHEN NO. 385-6