

30129
RENEW 31132 T29S R8W

FOUND - 1/4" IR ROD OUT OF GROUND AT
FENCE COR. TRUC

I FIND COLES 18" NOW 22" FIR 549' E
290 SHOWS GOOD BEARS IT DO NOT
OPEN ORIG. 15' DAK RECORD N77'E
SHOULD BE S77'E 69.9' SHOWS ROTTED
FACES NO SERRING FD. ORIG. 30" NOW
56.4' FIR 115.5' S80'W SHOWS GOOD
BARK SERRING. I ALSO FIND COLES
20" NOW 24" FIR STUMP N60°30'W
530'

I RESET 1. PIPE AT FENCE COR
CUT 3/4" I.R. ALONGSIDE.

NEW BTS

5" R. FIR BEARS N 63° W 64.7'
SCRIBED 530 CS BT
12" W. FIR BEARS S 87° W 27.3'
SCRIBED 531 T29S R8W CS BT
9" R. FIR BEARS N 61° E 13.7'
SCRIBED 520 T29S R8W CS BT

RENEW 1/4 COR 29 T29S R8W
B2

FOUND - 1/4" IR ROD @ BOTH BTS AS
SCRIBED BY BAYER 1939.
30" FIR NOW 34" FIR STUMP NR°E 550
NO SERRING FOUND "CUT LOW" 8" NOW
12" LABEL BLAZE NOT GROWN OVER
POINTS OF SCRIBING VISIBLE S38°E, 1180'

NOTE - 1/4" IR ROD AT CORNER IS IN CTR.
OF GRAVELLED ROAD @ ABOUT 3" UNDER
SURFACE.

NEW BTS

10' CEDAR BEARS N 124° E 53.2'
SCRIBED 1/4 529 CS BT
7' R. FIR BEARS S 65° E 56.9'
SCRIBED 1/4 532 CS BT

VAR. 205° OCT. 15-58
JTB.

DIETRZEN SP. 385-6

S.B.
C.S. File No. 49/100-42