

RENEW 7/10
11/15 T24S R5W

FOUND - NO SCRIBING FOUND FOR THIS CORNER. I DO FIND NO. 24 W. OAK THAT CHECKS BEARING DIST FOR ORIG. N. V. BT. 20 YEARS AGO CENTER COMPLETELY ROTTED. AND I FIND OAK STUMP HOLES THAT CHECK BEARINGS & DIST. FOR ORIG. NE. SEE # 5 W. B.TS. I ALSO FIND INSULATOR OVER 1/2" I.P. AT CORNER.

SET BRASS CAP AT CORNER MARKED COUNTY SURVEYORS OFFICE 1960.

59 | 510
516 | 515 - T24S R5W

NEW B.TS.

8" R. FIR BEARS N 72° W 38.5' SCRIBED S 9 T24S R5W C 3 BT

2" R. FIR BEARS N 57° E 36.0' SCRIBED S 10 T24S R5W C 3 BT

8" R. FIR BEARS S 74° W 54.0' SCRIBED S 16 T24S R5W C 3 BT

1" W. OAK BEARS S 37° E 22.0' SCRIBED S 15 T24S R5W C 3 BT

NOTE - NEW WIRE FENCE 5' NORTH.

FILED

RECEIVED

FEB 18 - 60

FEB 18 1960

M.G.
C.P.

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. 49/124-19

DIETZGEN NO. 389-S