

Renew S.E. cor. DLC 39 T245 R5W

Fd. cor. stone with faint chisel mks
as called for by FREQR & O.B.T. as follows
See Rev. #4 -

10" Now 26" W, 02K S, 38° W, 20 ± ft,

2 live - Rehealed scar - apparently
opened quite a few years ago -

we Rescribe "SE DLC 39 CS BT"

at cor. point in place of cor stone

set 1" I.P. & BRASS cap MKd. "COUNTY

SURVEYOR'S OFFICE 1970 T245

SE DLC — 39 R5W" & MK.

New B.T. -

14" W, 02K S, 2° E, 64 ± ft,

Mkd. "SE DLC 39 CS BT"

Reset old stone along side

BRASS cap - cor falls at fence

cor. - Thus x-x-x-x-x approx

300 ft. west of gate across old

Hiway 99.

April 10, 1970

V.P.T.
J.G.H.
V.D.P.
W.R.A. JR.

V.P.T. Ray

O.K.
J.W.D.B.
C.S. File No. 49/124

#17 -

103