

RENEW $\frac{43}{910}$ T 26 S R 7 W

FOUND - ORIG. 6" Now 32" W. FIR
S 35° E 29.7' CENTER ROTTED BUT
SHOWS GOOD REVERSE SCORING 2 S
W 0" ORIG. 10" Now 34" W. FIR
S 90° W 16.5' Now DOWN CENTER
ROTTED BUT SHOWS PARTS OF OLD
TRACE TO SCORING ED. FIND NO
TRACE OF ORIG. N W OR N E BTL
SET BRASS CAP AT CORNER NIKO.

59/55 T 26 S R 7 W COUNTY SURVEYORS
59/510 OFFICE 1959

NOTE - I FIND STEEL POST W/ID BY
NEARBY TO THE BOLLERS CORNER
BEARS S 71° E 16.5' FROM BRASS CAP
RESET STEEL POST ALONGSIDE BRASS CAP.

NEW BTL
10" R. FIR BEARS N 39° E 27.8'
SCRIBED S 3 T 26 S R 7 W CBRT

6" W. FIR BEARS N 65° W 30.8'
SCRIBED S 4 CBRT

12" W. FIR BEARS S 60° W 31.6'
SCRIBED S 9 T 26 S R 7 W CBRT

32" W. FIR BEARS S 35° E 29.7'
SCRIBED S 10 T 26 S R 7 W CBRT

VAR 20 ±°

AUG 26-59
U.P.
N.G.
D.P.

DIETZEN NO. 385-6

C. S. File No. 49/122-9