

Renew Closing Cor. $\frac{531}{532}$ T225 R6W
T235

Fd. 1955 Cad. BRASS cap - nearly
out of ground - properly MKd. - with
Haines "T" IRON alongside - we Reset
B.T.'s Recorded as found by Haines
see Ren. # 113 of T225 R6W - as follows

18" Fir N. $36\frac{1}{2}^{\circ}$ W. 45 $\frac{1}{2}$ ft.
Now Dead. Scribe visible - overgrowth
of 9 Rings -

24" Fir STUMP N. 20° E. 48 $\frac{1}{2}$ ft.
Scribe visible - ^oORIG cedar
B.T. gone - stump hole & TURNED
out TREE TO N.W. still in evidence -
we MARK New B.T. -

12" Hemlock N. 6° W. 47 $\frac{1}{2}$ ft.
MKd. "T225 R6W 531 CC CS BT"
No Trees close to N.E. - This
COR. lies ON VERY STEEP
NORTHERLY Slope APPROX 950 ft
South of squaw creek.

Dec. 23, 1969

VRT
JGH
VDP

VRT Tracy

#121-T22
456-T23-6

C. S. File No. $\frac{92}{102}$ -99