

SECTION CORNER $\frac{17}{20} \mid \frac{16}{21}$

T31S, R5W, WM

FOUND:

This corner falls in an old burn. Corner was set on the intersection of the original Blazes, then when the corner was occupied I turned off the correct bearings and distances to 4 old fir stumps that fit the bearings and distances to the 4 original bearing trees perfectly. No scribing remained on any of the old bearing trees.

SET:

3" Fir post from which I set the following new bearing trees.

6" Fir N 56° E 10.4' scribed S 16, T31S, R5W, BT

3" Fir N 55° W 18.3' scribed S 17, T31S, R5W, BT

22" Fir S 46° W 20.8' scribed S 20, T31S, R5W, BT

6" Fir S 83° E 39.6' scribed S 21, T31, R5W, BT

✓