

THE ROBERT DOLLAR CO.

COW CREEK DIVISION
GLENDALE, OREGON

TELETYPE GLENDALE 85

TELEPHONE 521

April 13, 1960

Douglas County Surveyor
County Courthouse
Roseburg, Oregon

Dear Sir:

The quarter corner common to Section 8 and 9, T 32 S, R 7 W, W. M. was found to be in very poor condition. Both original bearing trees had fallen over but the scribing was still visible.

I scribed two new bearing trees and marked the corner as follows. Marked the corner with a $1\frac{1}{4}$ " (O.D.) iron pipe driven 20" in the ground. A 12" Cedar S $89\frac{1}{2}^{\circ}$ W, 33.7 feet was referenced and scribed S $8\frac{1}{4}$ S 4186 BT. A 6" Cedar N $61\frac{1}{2}^{\circ}$ E, 13.1 feet was referenced and scribed S $9\frac{1}{4}$ S, 4186 BT.

Bearing trees were referenced with a compass and chain magnetic declination used was $19\frac{1}{2}^{\circ}$ E. Witnessed by Robert A. Harris and Milner Larson.

Yours very truly,

THE ROBERT DOLLAR CO.



Lorne Swearingen
Registered Engineer 4186

LS/jvd