

# THE ROBERT DOLLAR CO.

COW CREEK DIVISION  
GLENDALE, OREGON

TELETYPE GLENDALE 85

TELEPHONE 521

April 13, 1960

Douglas County Surveyor  
County Courthouse  
Roseburg, Oregon

Dear Sir:

The quarter corner common to Sections 14 and 23, T 32 S, R 8 W, W. M. was found to be in very poor condition. The corner was a stone which was still in place but badly broken. The original bearing tree for Section 13 had rotted away. The bearing tree for Section 23 is a pine snag broken off just above the scribed face.

I marked the corner with a 7/8" x 30" Hex drill steel driven 20" in the ground from which I referenced a 6" Laurel N 40 $\frac{1}{2}$ ° E 16.3 feet scribed  $\frac{1}{4}$  S 4186 BT, a 30" Fir S 20° E 42.4 feet scribed  $\frac{1}{4}$  S 4186 BT.

Bearing trees were referenced with a compass and chain, magnetic declination 19 $\frac{1}{2}$ ° E, witnessed by Robert A. Harris and Milner Larson.

Yours very truly,

THE ROBERT DOLLAR CO.

*Lorne Swearingen*  
Lorne Swearingen  
Registered Engineer 4186

LS/jvd