

THE ROBERT DOLLAR CO.

COW CREEK DIVISION
GLENDALE, OREGON

TELETYPE GLENDALE 85

TELEPHONE 521

February 18, 1960

Douglas County Surveyor
County Courthouse
Roseburg, Oregon

Dear Sir:

The quarter corner common to Section 31, T 31 S, R 8 W, W. M. and Section 6, T 32 S, R 8 W., W. M. was found to be in poor condition. The original bearing tree in Section 31, T 31 S, R 8 W, W. M. was felled in a clear cut logging operation. This tree had been barked scribed and the evidence of scribing visible before falling. The original bearing tree in Section 6, T 32 S, R 8 W, W. M. remains standing but is a snag. The original corner called for a stone (not found).

I set a 1" (inner diameter) iron pipe driven 18" into the ground for the quarter corner for Section 31, T 31 S, R 8 W, W. M. and Section 6, T 32 S, R 8 W, W. M. Since the area to the north has been clear cut and no trees available to scribe, a 40" Douglas Fir, S 58° E, 39.7' was referenced and scribed S 6 1/2 S, B. T.

Bearing tree was referenced with a compass and chain, magnetic declination used was 19 1/2° E. Witnessed by Robert Harris and Milner Larson.

Yours very truly,

THE ROBERT DOLLAR CO.

Lorne Swearingen
Lorne Swearingen
Registered Engineer 4186

LS/jvd

C. S. File No. 51/68-1