

# THE ROBERT DOLLAR CO.

COW CREEK DIVISION  
GLENDALE, OREGON

TELETYPE GLENDALE 85

TELEPHONE 521

April 13, 1960

Douglas County Surveyor  
County Courthouse  
Roseburg, Oregon

Dear Sir:

The quarter corner common to Section 31, T 31 S, R 8 W, W. M. and Section 36, T 31 S, R 9 W, W. M. was found to be in poor condition. The original bearing tree in Section 31, T 31 S, R 8 W was bark scribed and had been burned until the scribing was almost invisible. The bearing tree in Section 36, T 31 S, R 9 W, W. M. was rotted away and only the stump held remaining.

I set a 7/8" Hex drill steel 20" in the ground for the quarter corner. A 6" Douglas Fir N 61° W 26.1 feet was referenced and scribed S 36 1/4 S 4186 BT. A 36" Douglas Fir N 42° S 15.8 feet (old BT) referenced scribed 1/4 S 4186 BT.

Bearing trees were referenced with a compass and chain, magnetic bearing 19° 30' E. Witnessed by Robert A. Harris and Milner Larson.

Yours very truly,

THE ROBERT DOLLAR CO.



Lorne Swearingen  
Registered Engineer 4186

LS/jvd