

THE ROBERT DOLLAR CO.

COW CREEK DIVISION
GLENDALE, OREGON

TELETYPE GLENDALE 85

TELEPHONE 521

January 16, 1961

Douglas County Surveyor
Douglas County Courthouse
Roseburg, Oregon

Dear Sir:

The quarter corner common to Section 35 and 36, T 31 S, R 9 W, W. M. was found in poor condition. The original bearing tree for Section 35 is a 20" Cedar which has had the face destroyed by a logging slash fire. The original 10" fir tree for Section 36 has blown over but the original face is clearly visible.

I marked the corner with a 7/8" x 30" Hex drill steel driven 20" in the ground from which I referenced a 8" Fir N 28° W 54.5 feet scribed S 35 $\frac{1}{4}$ 4186 BT, a 10" Fir S 44° E 16.9 feet scribed S 36 $\frac{1}{4}$ 4186 BT.

Bearing trees were referenced with a compass and chain, magnetic declination 19 $\frac{1}{2}$ ° E witnessed by T. Mehl, III.

Yours very truly,

THE ROBERT DOLLAR CO.

Lorne Swearingen

Lorne Swearingen
Registered Engineer 4186

LS/jvd

FILED
RECEIVED

JAN 16 1961

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. 51/68-5