

UNITED STATES PLYWOOD CORPORATION

P. O. BOX 1328 • ROSEBURG, OREGON • PHONE OR 2-3331



MANUFACTURERS OF WELDWOOD PLYWOOD AND ALLIED PRODUCTS

1/4 Section Corner: Sections 22 and 23, T27S, R2W

Found: 1-1/2" Iron Pipe. This iron pipe was set by me in 1954 from the original bearing trees; subsequent logging destroyed all original bearing trees. I now set a 2 1/2" aluminum cap in place of the pipe and reference.

Set: 2 1/2" Aluminum Cap

60" Cedar stump North 37° West, 53.0 feet
Marked 1/4 S22 RE4287

30" Cedar stump, South 58° East, 39.6 feet
Marked 1/4 S23 RE4287

December 1962

✓ + ○

1/4 Section Corner: Sections 23 and 26, T27S, R2W

Found:

38" Hemlock stump, South 88° East, 16.5 feet

24" Hemlock stump, North 61° West, 14.5 feet

Scribing clear and legible. No other trees suitable for scribing within limits.

Set: 2 1/2" Aluminum Cap

December 1962

✓ + ○

1/4 Section Corner: Sections 23 and 24, T27S, R2W

Found:

18" Hemlock, South 85° East, 20.4 feet

10" Yew, North 80° West, 15.2 feet

Set: 2 1/2" Aluminum Cap

December 1962

○ +

FILED
RECEIVED

APR 10 1963

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

