

Renew Sec Cor. $\frac{521}{522}$ | $\frac{528}{527}$ T315 R6W

Fd. at Cor. one BT, alive. -

16" Cedar N. 44° W. 31 $\frac{1}{2}$ ft. Now 30"
chopped out & Face Rotted away - NO scribe.

The 15" Fir S. 45° E. 8 $\frac{1}{2}$ ft. is a

Rotted Stump, shows "27 W" BARK
scribe. N.E. & S.W. B.T.s are down

Burned & Rotting - NO scribe Fd. Set

at Cor. 1" I.P. & BRASS Cap MKd. -

"County Surveyors Office 1964

T315 R6W $\frac{521}{528}$ | $\frac{522}{527}$. & New BT's. -

8" W. Fir S. 56° E. 32 $\frac{1}{2}$ ft.

Mkd "T315 R6W 527 CS BT"

12" W. Fir N. 75° E. 40 $\frac{1}{2}$ ft.

Mkd. "T315 R6W 522 CS BT."

14" D. Fir S. 72° W. 17 $\frac{1}{2}$ ft.

Mkd. "T315 R6W 528 CS BT"

8" W. Fir N. 15° W. 30 $\frac{1}{2}$ ft.

Mkd "T315 R6W 521 CS BT"

Sept 11, 1964

V.R.T.
M.D.
J.B.

~~V.R. Tracy~~

C. S. File No. 52/25-22