

Renew $\frac{1}{4}$ ^{R1W} 525 R1E T255

Fd. 1927 G.L.O. BRASS Cap badly bent
& nearly out of ground. we straightened
& Reset. B.Ts as follows -

ORIG. 36" now 40" FIR S. 60° W. 20⁵ ft.

Now SW 29 - VERY good SCAR. do not open

1927 BT - 6" now 10" FIR N. 65° W. 34³ ft.

2 live shows good SCAR - we do not open.

also find ORIG. BRASS stone showing

"4" chisel MKS - we MARK New

BT. -

9" D. FIR S. 10 $\frac{1}{2}$ ° W. 23⁷ ft.

Mkd. " $\frac{1}{4}$ 525 CS BT"

This COR. lies on Moderate,
changing to Steep W. slope. & approx.

125 ft. North of the $\frac{1}{4}$ COR. of S. 30

of T255 R1E.

OCT, 18, 1966

V.R.T.

J.H.

D.W.

FILED

RECEIVED

OCT 18 1966

COUNTY SURVEYOR

DOUGLAS COUNTY, ORE.

C. S. File No. 52/30-33

67-T25-1W

* $\frac{1}{4}$ -R1E