

Renew $\frac{1}{4}$ $\frac{515}{522}$ T255 RIW

Fd. Aluminum Cap on steel pipe MKd.

"U.S. P.C. PROPERTY COR. RE. 4287

T255 RIW $\frac{1}{4}$ $\frac{515}{522}$ " & B.T.s as follows

See Ren. #50 -

16" Hemlock N, $73\frac{1}{2}^{\circ}$ E, 36° ft.

" $\frac{1}{4}$ 515 BT" scribe visible on unhealed blaze. - 2 live & good condition.

12" not 9" cedar S, 34° W, 7° ft.

2 live - Top broken off & severe injury to East half of Tree - scribe visible

ORIG. N-E, B.T. Now Turned out.

we MARK New B.T. -

22" Cedar S, 24° E. 33 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$ 522 cs BT"

This Cor. Lies approx 60 ft.

West of small creek course N.E.

Not SE, as called for in orig.

field notes -

OCT. 27, 1966

FILED

U.R.T.

RECEIVED

T.H.
D.W.

OCT 27 1966

*

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

#92

O.K. J.W.B.

C. S. File No. 52/30-40