

Renew Sec. Cor. $\frac{51}{512}$ T255 RIW & RIE

Fd. 1927 G.L.P. BRASS cap properly MKd,
& NEARLY out of ground - we Reset 12"
in ground & Build mound of Stone 15"
high around Pipe - B.T.s as follows -

ORIG. 60" Now 60" FIR S. 48° W. 19 $\frac{1}{2}$ ft.

Now Stump - Cut Low - No scribe.

ORIG. 30" Now 31" FIR N. 71° W. 26 $\frac{1}{2}$ ft.

Recorded To be 4 LKs, actually 40 LKs. - scribe
MKs. Visible on nearly hezled Blaze - alive
obliterated B.T.s to N.E. & S.E. Now Turned
out, we MK. New B.T.s -

11" W. FIR S. 74 ° W. 61 $\frac{1}{2}$ ft.

Mkd. "T255 RIW 512 CS BT"

5" Hemlock N. 59 ° W. 29 $\frac{1}{2}$ ft.

Mkd. "51 CS BT"

This cor. Lies at N.E. cor. of
cutoff unit on top of Round Spur
Sloping West.

Done 4, 1966

FILED
RECEIVED

V.R.T.
J.H.
D.W.

J.R. Tracy

NOV 4 1966

COUNTY SURVEYOR

DOUGLAS COUNTY, ORE

✓ #16-12
* #81-12
J.W.V.S.

C. S. File No. 52/30-51