

Renew $\frac{1}{4}$ $\frac{1}{2}$ 530 only of T265 R1W

Fd. B.T. 25 follows -

orig. 18" now 20" cedar N. 49° E. 165 ft.

2 live & shows old " $\frac{1}{4}$ 530 BT" scribe on unhealed blaze. No trace of S.E. BT

Due to cat logging. also find no trace of stone called for set 1" I.P. &

BRASS CAP MKD. COUNTY SURVEYOR'S

OFFICE 1966 T265 R2W $\frac{1}{4}$ 530 R1W

& MK. New BTs -

28" D. FIR S. 27 $\frac{1}{2}$ ° E. 66 $\frac{7}{8}$ ft.

MKD. " $\frac{1}{4}$ 530 CS BT"

8" Hemlock S. 77° E. 94 $\frac{5}{8}$ ft.

MKD. " $\frac{1}{4}$ 530 CS BT"

This cor. lies approx 60 ft S. of Thunder Mtn. Road.

May, 1966

V.R.T.
J.H.

**FILED
RECEIVED**

MAY 19 1966

**COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.**

$\frac{1}{4}$ 36-2W
#8-1W

C.S. File No. 52/77 $\frac{1}{4}$

O.K. J.W.B

See Card attached T26-2W

Section 30

Top 26 S

Base 1 W

N

Date: 3/26/66



How was corner identified? Stone not found & only one.

BT located

Condition of corner: Bad

Best route to reach corner: Thunder Mtn Road

Quadrant	NS	WN	ES	SW
Species & Size	<u>Revised 5/19/66</u>			
Dist. & Bearing				
Condition of Scribe	<u>K.R.H.</u>			
Original of Resurvey	<u>J.H.</u>			
Appearance of B.T.				
Tags, Marks, etc.	<u>CS 52/77-14</u>			

Other Remarks:

Corner apparently
destroyed by logging.
Needs iron pipe &
cap set. Mark new.

BT
[Signature]
 Signed