

Fd. O.K.
T2/65
R2W | R1W
14 525
only

DIETZGEN NO. 385-6

CS 52/77 - 15

Section 25 Twp 26 S Rge 2 W N

Date: 3/26/66

How was corner identified? Localed BT's - Good Condition.



Condition of corner: Poor ?

Best route to reach corner: Thunder Mtn Road,

Quadrant	NE	NW	SE	SW
Spools & Size	This Cor. found to be OK.			
Dist. & Bearing	As recorded in field notes			
Condition of Scribe	BRASS Cap solid. 5/19/66			
Original of Resurvey	A.R.T.			
Appearance of B.T.	J.M.			
Taps, Marks, etc.	CS 5247-15			

Other Remarks: BT's standing, markings overgrown, keep iron pipe + cap set

B. T. T.
Signed