

EAST 1/4 COR. 5 18 T 2 B S R 2 1/2

TO CORRECT BEARING & DIST.
OF N W BT, RECORD 40" CEDAR
N 56° W 40, SHOULD BE N 49° W
30.

J. B.

revised
notes

CS 62/79 - 8