

$\frac{35}{2} | \frac{36}{1}$

Corner common to Sections 35 and 36-22S-4W
Sections 1 and 2-23S-4W

2348

A preliminary search did not develop any evidence of this corner.

Following is a report on the survey work which was done to re-establish said corner.

By careful retracement of the Township line to the East and West, the Original Line Trees were found and the corner was re-established at the proportionate distance between these Original Line Trees.

To substantiate the location here used, the following record was made:

From Re-established Corner:

GLO Record 165' East to Line Tree - Weyerhaeuser Company Measurement 166'
GLO Record 165' West to Line Tree - Weyerhaeuser Company Measurement 166'
GLO Record 676' West to Line Tree - Weyerhaeuser Company Measurement 680'
GLO Record 5293' South to $\frac{2}{11} | \frac{1}{12}$ - Weyerhaeuser Company Measurement 5297'

GLO Record 2640' West to $\frac{1}{4}$ Corner 36 & 1 - Weyerhaeuser Co. Measurement 2648'

Other record distances:

From Line Tree East of re-established corner East to creek the GLO distance is 1152'; Weyerhaeuser Company distance is 1159'.

From said creek East to $\frac{1}{4}$ corner to Sections 36 and 1 the GLO distance is 1323'; Weyerhaeuser Company distance is 1323'.

Distances to creek to South, and to and between creeks to North indicate they were never accurately taken or recorded.

There is evidence of survey work done to the West and to the South which has not been recorded, and of current active survey work to the West.

$\frac{35}{2} | \frac{36}{1}$

Corner common to Sections 35 and 36-22S-4W
Sections 1 and 2-23S-4W

2349

GLO Survey Record

All evidence gone

County Survey Record

All evidence gone

Nailed a 3" x 3" piece of aluminum to a 12" Fir log for corner at proportionate distance between the following identified Original Line Trees:

48" Fir East 166' 2 Notches on East and West sides
42" Fir Stmp. West 166'

CS 53/1-51